Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

LNMLC029405B

abandoned wel	I. Use form 3160-3 (APD) for such p	roposals.	FEB 0724	1 1 maian, Anottee o	or tribe	Name	
SUBMIT IN TRII	PLICATE - Other instruct	ions on rev	erse side. 📙	OBBSU	7 If Unit or CA/Agre	ement, N	Name and/or No.	
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. GC FEDERAL 54			
2. Name of Operator Contact: CHASITY JACKS COG OPERATING LLC E-Mail: cjackson@conchoresources.c					9. API Well No. 30-025-39498-00-X1			
3a. Address 550 WEST TEXAS AVENUE S MIDLAND, TX 79701-4287	. (include area code 6-3087)	10. Field and Pool, or Exploratory MALJAMAR (250, W					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State			
Sec 19 T17S R32E SWSE Lot O 840FSL 1650FEL			,	İ	LEA COUNTY, NM			
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF 1	NOTICE, RE	PORT, OR OTHE	R DA	ГА	
TYPE OF SUBMISSION	F SUBMISSION TYPE OF ACTION							
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Well Spud Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)								
1/17/11 TD 17-1/2? @ 701?. Ran 17jts 13-3/8 H40 48# @ 701?. Cmt w/450sx C. lead, 200sx C. tail. PD @ 2:42PM. Circ 208sx. WOC 18 hrs. Test BOP to 2000# for 30 min., ok. 1/19/11 TD 11? @ 1912?. Ran 47jts 8-5/8 J55 32# @ 1912?. Cmt w/400sx C. lead, 200sx C. tail. PD @ 12:18AM. Circ 147sx. WOC 18 hrs. Test BOP to 2000# for 30 min, ok. 1/25/11 TD 7-7/8? @ 7120'. Ran 157jts 5-1/2 L80 17# @ 7115'. DV tool @ 3804. Cmt 1st stg w/600sx C. 1/26/11 PD @ 5AM. Circ 79sx. Cmt 2nd stg w/ 700sx C. lead, 300sx C. tail. PD @ 12:22AM. Circ 254sx WOC 24 hrs. RR. Will test csg to 5000# for 30 min on completion rig.								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #101825 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Hobbs								
Committed to AFMSS for processing by KUI			RT SIMMONS on 02/01/2011 (11KMS0217SE)					
Name (Printed/Typed) CHASITY JACKSON			Title PREPA	ARER				
Signature (Electronic S	ubmission)		Date 01/31/2	2011				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E			
Approved By ACCEPTED			JAMES A TitleSUPERVI			I	Date 02/04/2011	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Hobbs		For	FEB	0 8 2011		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a catalements or representations as t	crime for any pe to any matter w	erson knowingly an ithin its jurisdiction	d willfully to ma	ke to any department of	or agency	of the United	