## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT J 1625 N. French Dr. , Hobbs, NM 88240	EL1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-07556	
DISTRICT_II			5. Indicate Type of Lease	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210 FEB 10 2U11			STATE FEE X	
1301 W. Grand Ave, Artesia, NM 88210 FEB TO 2011  DISTRICT III  1000 Rio Brazos Rd, Aztec, NM 87410 HOBBSUCD			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 33  8. Well No. 411	
1. Type of Well:  Oil Well   Gas Well   Other Temporarily Abandoned				/
2. Name of Operator  Operator I Remains I tel			9. OGRID No. 157984	
Occidental Permian Ltd.  3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR I Box 90 Denver City, TX				
4. Well Location				
Unit Letter A : 660 Feet From The North 660 Feet From The East Line				
Section 33 Township 18-S Range 38-E NMPM Lea County  11. Elevation (Show whether DF, RKB, RT GR, etc.)				
	3642' GL	· · · · · · · · · · · · · · · · · · ·		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI	NS. PLUG & A	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	T JOB	
OTHER:			/TA Status Request	X
		171 Wellbeite		
<ul> <li>13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>1. RUPU &amp; RU.</li> </ul>				
2. RU wireline and perforate hole @4003'. RD wireline. This Approval of Temporary				
Abandonment Eyniron /-/3/0 //-				
4. POOH and lay down ESP equipment.  5. RIH w/bit. Tag @4030'. POOH w/bit.				
6. RIH w/CIBP set @4000'. RU HES & spot 80' of cement on top of CIBP. RD HES. Tag top of cement @3915'.				
7. ND BOP/NU cap flange wellhead.				
8. Test casing to 520 PSI for 30 minutes and chart for the NMOCD. Mark Whittaker with NMOCD on location for test.  9. RU & RU. Clean location.				
10. Well is Temporarily abandoned.			V	
	RUPU 01	/07/2011 RDPU 01/13/20	11	
Therefore and Code at the information of the single				
I hereby certify that the information above is t constructed or	.ue and complete to the best of my knowl	eage and belief. I further certify t	that any pit or below-grade tank ha	as been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved	
$\mathcal{T}$	La Orlina L	plan	L	
SIGNATURE   UNIVERSITY	+ Cifarmon	_ TITLE Administrative	Associate DATE	02/08/2011
	hnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only	J. <i>U</i> ]	<u></u>		7 1/2
APPROVED BY	yther	_ TITLE	F NEL DAT	E 2-14-201
CONDITIONS OF APPROVAL IF ANY:				