



IN REPLY REFER TO:

NM-2511  
3162.4 (P0220)

## United States Department of the Interior

Bureau of Land Management  
Carlsbad Field Office  
620 E. Greene Street  
Carlsbad, NM 88220  
www.nm.blm.gov

RECEIVED

FEB 14 2011  
HOBBSOCD

FEB 10 2011

EnerVest Operating, Ltd.  
1001 Fannin, Suite 800  
Houston, TX 77002-6707

Gentlemen:

Your Application for Permit to Drill (APD) the following referenced well has expired because drilling has not commenced within two years of the approval date as stated in Onshore Order #1.

NM-2511 Meyer B-28 A Com AC2 #7 660'S. & 842'E., sec. 28, T. 20 S., R. 37 E.  
APD approved on, October 29, 2008, APD expired on October 29, 2010

30-025-39239

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM, so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (1 original and 3 copies) to this office. Since the original APD has expired, the resubmitted APD will be subject to all the processing requirements including the 30-day posting requirement. Please note on the resubmitted APD that it was previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions please contact Betty Hill at (575) 234-5937.

Sincerely,

*J. D. Peterson*  
For Don Peterson  
Assistant Field Manager,  
Lands, & Minerals

bcc:  
P0222, I&E HFS  
NMOCD Hobbs

*Don*