Submit 3 Copies To Appropriate District State of New Mo	exico Form C-103
Office Energy, Minerals and Natu	
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District.II OIL CONSERVATIO	N DIVISION 30-025-34471
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Fra	ancis Dr. 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 8	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	OR PLUG BACK TO A Cuerno 4 State
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
Nearburg Producing Company	015742
3. Address of Operator	10. Pool name or Wildcat
3300 N A St., Bldg 2, Ste 120, Midland, TX 79705	Grama Ridge: Morrow East (Gas)
4. Well Location	
Unit Letter C : 660 feet from the No	rth line and 1750 feet from the West line
Continue A Township COC	Range 35E NMPM County Lea
Section 4 Township 22S  11. Elevation (Show whether	
	3624
Christophysical Control of the Market and the Section Section Control of Cont	
12. Check Appropriate Box to Indicate	Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO.	<u> </u>
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. P AND A
	CASING/CEMENT JOB
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER:	OTHER: recomplete to Morrow
OTHER: recomplete to Morrow  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
9/2/10 to 9/3/10 MIRU. POOH & LD rods and pump. 9/7/10 Tag sand above RBP. Circ sand off RBP @ 1: 9/8/10 Release RBP. POOH w/ RBP & tbg & LD.	1400'.
9/9/10 RIH & pump air and foam to clean out to pk	
9/10/10 to $9/13/10$ RIH w/ tbg and bail sand from	
9/14/10 to 9/17/10 RIH & wash sand off pkr. Latch	h up to pkr. LD swivel and press test on/off to 1000#.
	@ 12552-65'. WC perfs (10947-11110) remain above pkr
isolated from producing.	
Spud Date: Rig Rele	ease Date:
I hereby certify that the information above is true and complete to the	e best of my knowledge and belief.
SIGNATURE TI	TLE Regulatory Analyst DATE 2-16-11
	tstathem@nearburg.com mail address:PHONE_432/818-2950
FEB 1 8 2011	

\_DATE \_

APPROVED BY Conditions of Approval (if any):