

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br>30-025-29048                                                                        |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.                                                                        |
| 7. Lease Name or Unit Agreement Name<br>Christmas 7                                                 |
| 8. Well Number<br>2                                                                                 |
| 9. OGRID Number<br>147179                                                                           |
| 10. Pool name or Wildcat Monument, Tubb <i>Skaggs Grayburg</i>                                      |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)<br>GL: 3567.5'                                   |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Chesapeake Operating, Inc

3. Address of Operator  
P. O. Box 18496, Oklahoma City, OK 73154-0496

4. Well Location

Unit Letter A : 380 feet from the North line and 420 feet from the East line  
Section 7 Township 20S Range 38E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
GL: 3567.5'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Add'l Perfs ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/17/03 Perf San Andres 4118-58' -

Circ hole w/120 bbls 2% KCL wtr, POOH w/140 jts 2-3/8" tbg & 4-3/4" bit, RU Baker WL, perf San Andres 4118-58' @4 spf, 160 holes, 23 gram, .42" hole, RIH w/Arrow Set 1 pkr, SN & 1128 jts 2-3/8" tbg, set pkr @4033' KBM, start swab

2/18/03 RU Cudd Pumping Serv., pump 9 bbls 2% KCL wtr @1 BPM, pressure broke from 2920# to 2730#, acidize w/5000 gal 15% Ne-Fe acid, launch 160 ball sealers on last 2500 gal ISIP 1790#, 5 min 1590#, 10 min 1425#, 15 min 1195#, max PSI 3670#, avg PSI 3434#

12/20/03 14 hrs SITP 5800#, swab

rel pkr, POOH w/128 jts 2-3/8" tbg, SN & Arrow Set pkr, RIH w/CIBP 4087' KBM, POOH w/130 jts 2-3/8" tbg

12/21/03 RU Appelo, dump 10' cmt on CIBP, perf Grayburg 4010-34' @4 spf, 96 holes, 23 gram chgs, .42" hole, 90° phasing, RD Apollo, RIH w/Arrow Set 1 pkr, SN & 125 jts 2-3/8" tbg, set pkr @3941 w/13,000# compression, swab

Continued 2nd Page

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Andrew J. McCalmont TITLE Asset Manager DATE 02/11/04

Type or print name Andrew J. McCalmont E-mail address: Telephone No. (405) 848-8000

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER  
Conditions of approval, if any:

D FEB 27 2004

Page 2 C-103

Christmas 7 #2, API 30-025-29048, Lea Co., NM

12/22/03 15 hr SITP 450#, bleed off, start swab, IFL 1600', swab 25 BW in  
1 hr, RU Cudd, load backside w/15 bbls 2% KCL, pressure to 500#, OK, load  
tbg w/12 bbls 2% KCL, pump into 5 BPM @2700#, acidize Grayburg w/1500 gal  
7.5% Ne-Fe, launch 100 balls, no actions, ISIP 1500#, 5 min 317#, 10 min  
0#, avg rate 6.2 BPM, avg PSI 3355#, max PSI 3384#, start swab

