Office Office	State of New Mexico	Form C-103
District I Energy	, Minerals and Natural Resources ONSERVATION DIVISION ONSERVATION DIVISION South St. Francis Dr. Santa Fe, NM 87505	WELL API NO.
District II 1625 N. French Dr., Hobbs, NM 88240 District III 1301 W. Grand Ave., Artesia, NM 882 10 District III 1000 Rio Brazos Rd., Aztec, NM 803 10 District IV	ON GERRAL WICH BY WATCH	30-025-00291
District II 1301 W. Grand Ave., Artesia, NM 882 69 District III 1000 Rio Brazos Rd., Aztec, NM 8 9 0 5 20 1 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	ONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8440	20 South St. Francis Dr.	STATE X FEE (
District IV 1220 S. St. Francis Dr. Santa Fe. NM	Santa Fe, NM 8/303	6. State Oil & Gas Lease No.
		303735
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Rock Queen Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Monitor well		8. Well Number 4
2. Name of Operator Celero Energy II, LP		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601		10. Pool name or Wildcat
Midland, TX 79701		Caprock; Queen
4. Well Location		
Unit Letter K: 1980 feet from the S line and 1980 feet from the W line		
	ownship 13S Range 32E	NMPM CountyLea
11. EJevatio	on (Show whether DR, RKB, RT, GR, etc.	100000000000000000000000000000000000000
The state of the s		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE P	LANS COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE	COMPL CASING/CEMEN	T JOB 🗌 -
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER: Convert	TA'd well to monitor well
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
1/24/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" OD tbg WS & retrieving head for RBP. Wash off sand & latch onto RBP @ 3000', pull out of hole, LD 2 7/8" OD tbg WS w/ RBP. TIH w/ 95 jts of 2 3/8" OD 4.7# 8rd EUE J-55 IPC tbg w/ 7"plastic coated		
model AD-1 tension pkr. With pkr swinging @ 3008' displace annulus w/ pkr fluid. Set pkr w/ 13 pts of tension @ 3008'. (OH 3065-		
3071'). Test annulus w/ 500# pressure & held okay.		
2/23/11 - MIRU. NDWH. Pulled 35K tension on 7" pkr. NUWH. Ran OCD required MIT test. Tested 31 min @ 500# & held okay.		
Original chart is attached. Well now a monitor well as per Order No. R-1541-B.		
Ι.]	
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
thereby certify that the information above is true and complete to the best of my knowledge and benef.		
2 . 4/1+		
SIGNATURE TITLE Regulatory Analyst		DATE 02/24/2011
Type or print name Lisa Hunt	E-mail address: lhunt@celeroene	ergy.com PHONE: (432)686-1883
For State Use Only		
APPROVED BY: Stand TITLE STAFF NOT DATE 2-28-2011		
Conditions of Approval Hany):		
	•	

