

RECEIVED

Submit 1 Copy To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
 CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04018
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Rhombus Operating Co., Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 8316 midland, Tx 79708-8316		7. Lease Name or Unit Agreement Name Northwest Evmont Unit
4. Well Location Unit Letter P feet from the line and Section 15 Township 19S Range 36E NMPM County Lea		8. Well Number 117
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3744 GL 3756 HB		9. OGRID Number 19111
10. Pool name or Wildcat Evmont Yates 70vrs Queen		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
 PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: **TA (Amended Report)** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 12/17/10 - Set CFBP @ 4052' (top of reef @ 4102') dump bail 35' limit on top of plug. New PBD @ 4017'.
- 12/18/10 - Circ well w/100 bbls of fluid. Test to 500#. OK. LD +bs. Test to 500#. OK.
- 1/4/11 - Conduct T/A status Test w/OCD per Mark Whitaker present. Press to 580#, held for 30 min w/no leakoff or gain. Test Good. ~~Chart Attached~~

Spud Date:

Rig Release Date:

Per- E.L. Gonzales

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Tony Bunch

TITLE

Operations Manager

DATE

1/5/11

Type or print name

Tony Bunch

E-mail address:

t48bunch@yahoo.com

PHONE:

575-370-4313

For State Use Only

APPROVED BY:

E. L. Gonzales

TITLE

State Manager

DATE

3-14-2011

Conditions of Approval (if any):

This Approval of Temporary
 Abandonment Expires **1-4-2013**