Office State of New Mexico District Energy, Minerals and Natural Resources	Form C-103 October 13, 2009		
1625 N. French Dr., Hobbs RECEIVED District II 1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION	WELL API NO / /		
1301 W. Grand Ave., Artesia, NM 88210         OIL CONSERVATION DIVISION         District III         1000 Rio Brazos Rd., Aztee, NM 87410         Santa Fe, NM 87505	5. Indicate Type of Lease STATE FEE F		
District IV 1220 S. St. Francis Dr., SamOBBSOCD 87505	6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State GRV		
1. Type of Well: Oil Well   Gas Well   Other     2. Name of Operator	8. Well Number 001		
Endeavor Energy Resources, LP	190595		
3. Address of Operator 110 N. Marienfeld, Ste 200 Midland, TX 79701	10. Pool name or Wildcat SALADO DRAW; WOLFCAMP (GAS)		
4. Well Location			
Unit Letter G       : 1980       feet from the NORTH       line and 1980       feet from the EAST       line         Section 17       Township 26S       Range 33E       NMPM       CountyLEA       Image: CountyLEA			
Section 17       Township 26S       Range 33E       NMPM       CountyLEA         11. Elevation (Show whether DR, RKB, RT, GR, etc.)       3267.9       3267.9			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			
OTHER: OTHER:			
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>			
3/10/11 - 3/14/11 - Move rig to well and spot rig, set matting boards, cat walk & pipe racks. R/U Unit & reverse unit. Unload & tally 2 3/8" tbg. & 2 7/8" tbg. N/D capping flange, N/U 2' spacer spool and 11" 5000# Hyd BOP. R/U floor & tongs. M/U 4 1/8" bit on 6 - 3 1/8" drill collars and RIH w/16 jts 2 3/8" N-80 tubing , x-over to 2 7/8" tbg and RIH w/235 joints 2 7/8" tubing to 7890'. Cont. RIH w/tbg and bit, to tag @ 11,897'. R/U swivel & stripper head. Drilling on junk inside 5 1/2" liner @ 11,897', we were getting back small pieces of metal, we made about 6" all day. L/D swivel & stripper head. POH w/tbg to 5000'.			
Spud Date: Rig Release Date:			
I hereby certify that the information above is true and complete to the best of my knowledge	and baliaf		
SIGNATURE DATE 03/15/2011			

Type or print name Jenifer Sorley	E-mail address: Jenifer@eeronline.com	PHONE: (432)262-4014
For State Use Only	7	· · ·
APPROVED BY:	TITLE STAFF MAR	DATE 3-16-2011
Conditions of Approval (if any)		
Ċ		