

Submit 1 Copy To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88201

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico

Minerals and Natural Resources

Form C-103

October 13, 2009

RECEIVED

MAR 31 2011

HOBBSOCD

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. 30-025-01722
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> <i>FEE</i>
6. State Oil & Gas Lease No. LC065447
7. Lease Name or Unit Agreement Name TEAS YATES
8. Well Number <i>#32 32</i>
9. OGRID Number 0196069
10. Pool name or Wildcat TEAS YATES - SEVEN RIVERS
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3601GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other *Inj.*

2. Name of Operator  
MOMENTUM OPERATING CO., INC.

3. Address of Operator  
P.O. BOX 2439 ALBANY, TX 76430

4. Well Location  
Unit Letter *J* : *2310* feet from the *S* line and *1980* feet from the *E* line  
Section *13* Township *20S* Range *33E* NMPM County *LEA*

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2-14-11 MIRU Pull tubing, RU wireline & set CIBP at 3220', bailed 35' cement on top. Circulate well w/ mud. Perforate & squeeze a 100sx plug @ 3150' WOC SDFD

2-15-11 Tagged cement @ 3007'. Perforate & squeeze 40 sx cement plug @ 1620'. WOC & tagged @ 1445'. Perforate & squeeze 300 sx @ 1050'-surface  
2-22-11 Cut well head off 3' BGL & weld steel plate on casing & install dry hole marker

Well plugged & abandoned 2-15-11 Witnessed by BLM Representative  
Kathy Haston

Spud Date:

Rig Release Date:

CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection".

I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNATURE

*Ted Tidwell*

TITLE Agent

DATE 3-21-11

Type or print name Ted Tidwell

E-mail address:

PHONE: (325) 762-3331

For State Use Only

ted@momentumoperating.com

APPROVED BY:

*[Signature]*

TITLE

*STAFF WORK*

DATE 4-4-2011

Conditions of Approval (if any):