Submit 3 Copies To Appropria	To Appropriate District State of New Mexico			Form C-103	
District I	Office State of New Mexico State of New Mexico			June 19, 2008 WELL API NO.	
DISCRETE OF THE PROPERTY OF TH				i	5-09787
1301 W. Grand Ave., Artesia 1978 882 10 2011 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.				5. Indicate Type	of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87418 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505				STATE [☐ FEE ☒
1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Ga	us Lease No. 06443
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name Cooper Jal Unit	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injector				8. Well Number 211	
2. Name of Operator				9. OGRID Number 263848	
Resaca Operating Company					/
3. Address of Operator 2509 Maurice Road, Odessa, TX 79763				10. Pool name or Wildcat Jalmat; T-Y-7R/ Langlie Mattix; 7R-Q-G	
4. Well Location					
		eet from the <u>Sou</u> nship 24S R	th line and 36E	2310 feet from NMPM Lea	/
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3312' GL					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL \		•	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON					P AND A
PULL OR ALTER CASIN DOWNHOLE COMMING		COMPL	CASING/CEMENT	JOB 🗌	
OTHER:			OTHER: Clear	out & Acidize Injec	ctor 🖂
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
 MIRU Pulling Unit and Above Ground Steel Pit. 3/18/11 POOH w/ 2 3/8" tubing and 4" x 2 3/8" Baker AD-1 Tension Packer. RIH w/ 3 ¼" Bit & 6- 2 3/8" Drill Collars on 2 3/8" work string. RU swivel and cleaned out well down to TD @ 3600'; RIH w/ packer and set @ 2911'. Acidized OH 3001'-3600' w/ 20,000 gallons 90/10 Acid/ Xylene Mixture of NEFE 15% plus 14,000#'s salt. POOH w/ 2 3/8" work string; RIH w/ 2 3/8"IPC tubing; Ran preliminary MIT, held. RDMO Pulling Unit, cleaned location, cleaned and disposed of pit fluids. 3/23/11 Ran Post Workover MIT, held; pulled chart for NMOCD. (chart not witnessed) 3/24/11 					
Spud Date:	3/18/11	Rig Release D	ate: 3	/23/11	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
Thereby certify that the mi	formation above is true a	na complete to the b	est of my knowledge	and belief.	
SIGNATURE TITLE Engineer Assistant DATE 4/1/11					
Type or print name Melanie Reyes E-mail address: melanie.reyes@resacaexploitation.com PHONE: (432)580-8500					
APPROVED BY:	Emay he	TITLE ,	STAFF ME	DAT	TE 4-6-2011
Conditions of Approval (if any):					

