| "Office " | e of New Mexico | Form C-103 |
|---|---|---|
| District Energy, Minerals and Natural Resources | | October 13, 2009 |
| District II 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 882104 District III 1220 South St. Francis Dr. | | WELL API NO. 30-005-29148 |
| | | 5. Indicate Type of Lease |
| District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fe, NM 87505 | | STATE FEE X |
| District IV Santa Fe, NM EB Z7 Z011 Santa Fe, NM EB 1220 S. St. Francis Dr., Santa Fe, NM EB Z7 Z011 Santa Fe, NM EB | ta Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NNED 4 | | |
| 87505 SUNDRY NOTCES AND REPOR | TS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | Rock Queen Unit |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection | | 8. Well Number 304 |
| 2. Name of Operator Celero Energy II, LP | | 9. OGRID Number 247128 |
| 3. Address of Operator 400 W. Illinois, Ste. 1601 | | 10. Pool name or Wildcat |
| Midland, TX 79701 | | Caprock; Queen |
| 4. Well Location | | |
| | n the S line and 223 | 30feet from the _Eline |
| Section 25 Townsh | | NMPM CountyChaves |
| | ow whether DR, RKB, RT, GR. etc., | |
| | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | |
| NOTICE OF INTENTION TO: | SUB | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABAI | | |
| TEMPORARILY ABANDON CHANGE PLANS | | ILLING OPNS. 🗌 PAND A 🗌 |
| PULL OR ALTER CASING 🛛 MULTIPLE COM | PL 🗌 CASING/CEMEN | т јов 🔲 |
| | | |
| | | nnletion |
| OTHER: OTHER: Well completion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date | | |
| of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | |
| of starting any proposed work). SEE RULE 19 | 9.15.7.14 NMAC. For Multiple Co | mpletions: Attach wellbore diagram of |
| of starting any proposed work). SEE RULE 19 | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's 8 | mpletions: Attach wellbore diagram of & 4 ¾" bit. Tag @ 2516'. RU swivel. D/O DV |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" tool @ 2516'. Lower bit & D/O float collar @ 3072' | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. | mpletions: Attach wellbore diagram of 2 4 ¾" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rai charges. 2 SPF. 0 degree phasing. 0.46" hole from 3 | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH y | mpletions: Attach wellbore diagram of & 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH y l across perfs 3046-48'. Raise pkr to | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2 2875'. Broke down perfs w/ 810#. Acidized |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rai charges. 2 SPF. 0 degree phasing. 0.46" hole from 3 | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2 2875'. Broke down perfs w/ 810#. Acidized |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIP | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 | mpletions: Attach wellbore diagram of 2 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Ratcharges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50-7/8" ball sealers & flushed w/ 21 BFW. No or | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as | mpletions: Attach wellbore diagram of 2 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as | mpletions: Attach wellbore diagram of & 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIP 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No ov 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * C | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet | mpletions: Attach wellbore diagram of 2 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Ratcharges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50-7/8" ball sealers & flushed w/ 21 BFW. No or | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as | mpletions: Attach wellbore diagram of 2 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIP 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No ov 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * C | P.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 werflush. Treating pressures were as Continued on attached sheet Rig Release Date: | mpletions: Attach wellbore diagram of & 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. > 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rai charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No ov 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * (| P.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH v l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIP 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No ov 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * C | P.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH v l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rai charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No or 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * C Spud Date: | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3092 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 ½" csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 werflush. Treating pressures were as Continued on attached sheet Rig Release Date: WFX - 92 omplete to the best of my knowledge | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" (tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rai charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No ov 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * (| P.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH v l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 $\frac{1}{2}$ " csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: | mpletions: Attach wellbore diagram of 2 4 ³/₄" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹/₂" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹/₂" AD-1 tension pkr. 2875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" of tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No or 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * O Spud Date: | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3092 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 ½" csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: WFX - 928 omplete to the best of my knowledg TITLE Regulatory Analyst | mpletions: Attach wellbore diagram of & 4 ¾" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ½" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ½" AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = DATE 02/24/2011 |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" of tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No or 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * O Spud Date: I hereby certify that the information above is true and co SIGNATURE | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3095 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 ½" csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 werflush. Treating pressures were as Continued on attached sheet Rig Release Date: WFX - 982 omplete to the best of my knowledge | mpletions: Attach wellbore diagram of & 4 ¾" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ½" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ½" AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = DATE 02/24/2011 |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" of tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No or 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * O Spud Date: | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3092 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 ½" csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: WFX - 928 omplete to the best of my knowledg TITLE Regulatory Analyst | mpletions: Attach wellbore diagram of & 4 ³ / ₄ " bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ¹ / ₂ " csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ¹ / ₂ " AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = DATE 02/24/2011 ergy.com PHONE: (432)686-1883 |
| of starting any proposed work). SEE RULE 19 proposed completion or recompletion. 2/7/11 - MIRU. NDWH & NUBOP. TIH w/ 2 7/8" of tool @ 2516'. Lower bit & D/O float collar @ 3072' 2/8/11 - Ran GR/CCL/CBL from 2050' to 3095'. Rat charges, 2 SPF, 0 degree phasing, 0.46" hole from 3 Ran pkr to 3052'. Spot 100 gals of 7.5% NEFE acid perfs w/ 750 gals (includes the 100 gal of spot acid) = 120#, avg = 430# w/ an avg rate of 4.0 BPM. ISIF 2/9/11 - Ran BHP survey @ 3047'. TOH w/ tbg & p 0.46" hole from 3053' to 3067'; 15' & 30' holes. Set & 50- 7/8" ball sealers & flushed w/ 21 BFW. No or 240# @ 4.5 BPM. ISIP = 0#. TLTR = 90 bbls. * O Spud Date: I hereby certify that the information above is true and co SIGNATURE | 9.15.7.14 NMAC. For Multiple Co OD tbg WS w/ 6- 3 1/8" OD DC's & & ran bit to 3085'. Circ hole clean. n GR/CCL/CNL from 2000' to 3092 046' to 3048' = 3' & 6' holes. TIH w l across perfs 3046-48'. Raise pkr to & flushed w/ 17 BPW, no overflush P = vac. TLTR = 59 bbls. okr. Perf 5 ½" csg w/ 4" cased gun, pkr @ 2875'. Acdz perfs 3046-48 verflush. Treating pressures were as Continued on attached sheet Rig Release Date: WFX - 928 omplete to the best of my knowledg TITLE Regulatory Analyst | mpletions: Attach wellbore diagram of & 4 ¾" bit. Tag @ 2516'. RU swivel. D/O DV TOH w/ tbg, DC's & bit. 5'. Perf 5 ½" csg w/ 4' cased gun, 19 gram w/ 2 7/8" OD WS & 5 ½" AD-1 tension pkr. 2 875'. Broke down perfs w/ 810#. Acidized h. Treating pressures were max = 1100#, min 19 gram charges, 2 SPF, 0 degree phasing , ' & 3053-67' w/ 1500 gals of 7.5% NEFE acid follows: Max = 3000#. Min = 85#, Avg = DATE 02/24/2011 |

Rock Queen Unit #304 – C103 continued

2/10/11 - Release pkr, lower below perfs 3046-63' & knocked off ball sealers. TOH, LD 2 7/8" tbg WS & pkr. TIH w/ 93 jts (3008') of 2 3/8" OD 4.7# 8rd EUE J-55 IPC tbg w/ Hunting's special thread lubricant + 5 ½" nickel plated AS1-X pkr w/ 1.5" "F" profile nipple & on/off tool. Ran & set pkr @ 3008'. Release on/off tool from pkr, circ pkr fluid, latched back onto pkr, pulled 14,000# tension & test annulus w/ 500# for 30 min, held okay. NDBOP & NUWH. Installed 7 1/16" 3K flanged tbg head w/ 2 1/16" 5K tbg valve w/ nickel plated injection tee. Connect for injection. Well now ready for injection as per Order No. R-1541-A.

2/14/11 - Ran OCD required MIT test. Tested for 30 mins 540#. Tested okay. Original chart is attached. Approval was given by Maxey Brown w/ OCD to run test.

