

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBBS OCD OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

6. If Indian, Allottee or Tribe Name

5. Lease Serial No. NMNM12006

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an MAY 0 2 2011 abandoned well. Use form 3160-3 (APD) for such proposals.

	· · · · · · · · · · · · · · · · · · ·					
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. PIPELINE DEEP UNI		
1. Type of Well				8. Well Name and No. PIPELINE DEEP UNIT FEDERAL 001		
Oil Well Gas Well Other					NIT FEDERAL OUT >	
2. Name of Operator Contact: NATALIE E KRUEGER CIMAREX ENERGY CO. OF COLORAD@ail: nkrueger@cimarex.com				API Well No. 80-025-24470		
3a. Address 600 N. MARIENFELD ST., ST MIDLAND, TX 79701	3b. Phone No. (include area o Ph: 432-620-1936 Fx: 432-620-1940	620-1936 (ploratory ORROW (GAS)		
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description)	. /	11.	County or Parish, and	l State	
Sec 17 T19S R34E Mer NMP		L	EA COUNTY, NN	1		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE C	OF NOTICE, REPOR	T, OR OTHER I	DATA .	
TYPE OF SUBMISSION		ТҮРЕ	E OF ACTION		· · · · · · · · · · · · · · · · · · ·	
- Notice of Intent	Acidize	Deepen	☐ Production (S	tart/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction			Other	
Final Abandonment Notice	☐ Change Plans	Plug and Abandon	_		<u>م</u> - · · · · ·	
	Convert to Injection	Plug Back	☐ Water Dispose			
following completion of the involved testing has been completed. Final At determined that the site is ready for fit Well record sundry to docume 05-04-07. RIH with swab to che 05-04-07 Pumped 10 bbl dow back. Ran 2.375 inch WL gra 05-07-07 Pulled 120K#. Turn 05-09-07 Pumped 40 bbls 2% 05-10-07 Tagged sand line wagain @ 2700. Lost again. 05-11-07 Fishing with rods. Trecovery. 05-12-07 Using 10 foot spear	pandonment Notices shall be filed inal inspection.) ent previous work: neck FL. Parted line. Left 1 in tubing. Pulled 100K# on b and tagged @ 2275. Rained with tongs and got all tube down tubing. Could not sith spear using rods @ 197 agged sand line @ 3025, reformed. Tagged @ 2910.	only after all requirements, in 1700 feet of line in tubir tubing. Turned 4 turns i 2.375 inch WL grab an rns back. ting out with packer. 5. Pulled up 400 feet an no recovery. Tagged aga	eluding reclamation, have ng right, got 4 turns nd could not get fish. nd lost it. Tagged ain @ 3175, no	ACCEPTE APR	D FOR RECOR	
14. I hereby certify that the foregoing is	Electronic Submission #10	6362 verified by the BLM Y GY CO. OF COLORADO,	Well Information Systems sent to the Hobbs	BUREAU O CARLS	F LAND MANAGEMEN BAD FIELD OFFICE	
Name(Printed/Typed) NATALIE I	E KRUEGER	Title REG	ULATORY ANALYS	Т		
Signature (Electronic S			2/2011			
	THIS SPACE FOR	FEDERAL OR STAT	E OFFICE USE			
Approved By	. _	Title	PETROLEM	1 BAKINELL	Date MAY 03	
onditions of approval, if any, are attached ertify that the applicant holds legal or equ hich would entitle the applicant to condu		1	Ca			
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a creatatements or representations as to	ime for any person knowingly any matter within its jurisdict	and willfully to make to a	any department or ago	ency of the United	



Additional data for EC transaction #106362 that would not fit on the form

32. Additional remarks, continued

feet long. 05-15-07 Fishing with screw grab on rods. Tagged @ 2450, caught, and lost. Tagged @ 2300, caught and lost.

05-16-07 RIH with 2.375 inch screw barb abd tagged @ 2125, no recovery. Tagged again, no catch.

Hit tight spot @ 35 and would not go through.

08-02-07 POOH with estimated 11000 feet of sand line.

08-03-07 Chemical cut tubing @ 13153 leaving estimated 50' swab line, bar, and jars below packer in 10 feet of 2.875 inch tail pipe.

08-05-07 Re-set tubing, new and used. See detail below.

From 08-05-07 to 10-16-07, swabbed intermittently with plunger.

10-16-07 Removed plunger and swabbed dry. Turned to sales.

Tba: 2.875 inch Subs. 8'10' to 18.00; 279 Jts. 2.875 inch L 80 8Rd EUE to 5059.00; X Over. 8 Rd to DSS HT to 5060.00; 248 Jts. 2.875 inch DSS HT, 6.5# to 13086.00; X Over & 2.31 inch F Nipple to 13086.00; 1 Jt. Of 2.875 inch L80 8RD EUE to 13118.19; 5.5 inch Md. E 22 Anchor Seal Assembly to 13119.04; FB 1 Retainer Prod. Packer to 13122.14; 4 inch Millout Ext. to 13128.05; 4 inch X Over to 2.875 inch EUE to 13128.73; 2.875 inch Tbg., Jet cut on Btm. to 13148.73.