Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources District II CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 8840 1220 South St. Francis Dr. District III 1200 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		Form C-103 May 27, 2004
		WELL API NO.
		30-025-28783
		5. Indicate Type of Lease STATE FEE S
		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		301210
87505 SUNDRY NELCES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name JACKSON 5
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other		8. Well Number 002
2. Name of Operator		9. OGRID Number 232611
SUNDOWN ENERGY LP 3. Address of Operator		10. Pool name or Wildcat
13455 NOEL RD, STE. 2000, DALLAS, TX 75240		SCHARB; BONE SPRING
4. Well Location		
Unit Letter G : 2180 feet from the N line and 1980 feet from the E line Section 5 Township 19S Range 35E NMPM County LEA		
Section 5 Township 19S Range 35E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
GL 3869.8'		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material		
12. Check Appropriate Box to Ind	licate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING REMEDIAL WORK REMEDIAL WORK REMEDIAL WORK REMEDIAL WORK ALTERING CASING REMEDIAL WORK REMEDIAL WO		
PULL OR ALTER CASING DIMUTIPLE COMPL		
OTHER: OTHER: RETURN TO PRODUCTION Image: Complete and the state a		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
1) MIRU PU. 2) Drill out CIBP @ 9320', 9610' & 9985'.		
3) Clean out well bore to PBTD of 10,166'.		
4) RIH w/ pumping assembly to PBTD. LD 1 jt. Set TAC. SN @ 10,102'. EOT (2-7/8") @10,138'.		
5) RIH w/ pump & rods. Set ppg unit. Return well to production 1/9/11.		
6) Current test: 17 BW, recovering load water.		
I hereby certify that the information above is true and complete grade tank has been/will be constructed or closed according to NMOCD g	e to the best of my knowledg midelines □, a general permit □	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
	TITLE frod. Aufo	DATE <u>5-2-201</u>
	E-mail address:	Telephone No. 432-943 - 8770
For State Use Only	1	
APPROVED BY: Company TITLE STATE MGZ DATE 5-3-2011		
Conditions of Approval (if any):		
		MAY 0 4 2011

WELL DATA SHEET



٠,

WELL DATA SHEET

