Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. / 30-025-09025
District II 1301 W. Grand Ave., Artesia, HOBBS O	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
	1220 South St. Francis Dr.	STATE X FEE
District IV MAY 1 1220 S. St. Francis Dr., Santa Fe, NM 87505	ZUII Santa Fe, NM 87505	6. State Oil & Gas Lease No. A-2614
SUNDRECEN	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS. DIFFERENT RESERVOIR: USE "APPLIC. PROPOSALS.)	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	S. Eunice (RQ) Unit
	Gas Well X Other	8. Well Number 427
2. Name of Operator Apache Corporation		9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste.	3000, Midland, TX 79705	South Eunice (Seven RQ)
4. Well Location		
		feet from the <u>N</u> line
Section 25 Townshi	<u> </u>	County Lea
con the second	11. Elevation (Show whether DR, RKB, RT, GR, etc GL 3449'	
Pit or Below-grade Tank Application D or		
Pit typeDepth to Groundwat	erDistance from nearest fresh water well Distan	nce from nearest surface water N/A
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material		
12. Check Ar	ppropriate Box to Indicate Nature of Notice	e Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PULL OR ALTER CASING		
OTHER:		
13. Describe proposed or comple	ted operations. (Clearly state all pertinent details, and	nd give pertinent dates including estimated date
of starting any proposed work	k). SEE RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion
or recompletion.		
4/21/11MIRU plugging equipment. 4/22/11Tag existing 4 1/2" CIBP w/35 ft. of cmt @ 3608'. Circ. 62bbls, MLF.		
4/22/11 1 ag existing 4 1/2 CIBF w/35 it. of cmt @ 3006'. Circ. 6200is, MLF. 4/25/11Spot 25 sxs plug @ 2977' est top of cmt @ 2615'. Perf a 2396' 4 ½" pkr @ 2018'. Could not pump into perfs.		
Drop 50' below 2396' to 2446' & spot 25 sxs cmt woc tag cmt. plug @ 2094'.		
Perf hole @ 1568' 4 1/2" pkr @ 1198'. Could not pump into perfs.		
4/26/11Spot 25 sxs from 1618' woc tag cmt plug @ 1280' perf @ 482' squeeze 60 sxs – tag @ 160'. Perf @ 60' squeeze 25 sxs cmt plug @ surface.		
Cut off WHA anchors. Install dry hole marker. Clean location.		
hole marker. Clean location.		
		·
I hereby certify that the information at grade tank has been/will be constructed or ch	bove is true and complete to the best of my knowled sed according to NMOCD guidelines ⊠, a general permit □	ge and belief. I further certify that any pit or below-] or an (attached) alternative OCD-approved plan [].
SIGNATURE	TITLE P & A Supervisor (Basic Energy Services) DATE <u>5-3</u> -1(
Type or print name:	E-mail address:	
For State Use Only		Telephone No. 432-563-3355
Stat-		
APPROVED BY: Conditions of Approval (if any):	TITLE JTANY ME	DATE 5-12-2011
Conditions of Approval at any		
\bigcirc	Approved for plussing of the	j –
	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Part	/
		(
	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	•