Submit 3 Copie Office	es 10 Appropriate Dist		State of New M			rm C-1
District I	. D. H.M. 351007	0.	, Minerals and Na	tural Resources	WELL API NO.	ine 19, 2
1625 N. French District II	1 Dr., Hobbs, NM 8824	Orre and	ONIGEDY ! CTC	N DILITORON	30-025-26169	
1301 W. Grand District III	l Ave., Artesia, NM 88	210 VELL C	CONSERVATIO	N DIVISION	5. Indicate Type of Lease	/
1000 Rio Braze	os Rd., Aztec, NM 874	IA :	220 South St. Fr		STATE 🗵 FEE	
District IV	WI<i>F</i> ncis Dr., Santa Fe, NM		Santa Fe, NM	8/303	6. State Oil & Gas Lease No.	
87505					B-1428	
(DO NOT LICE	SUNDRY	ECENCO ND RI	EPORTS ON WELI	LS NAME BACK TO A	7. Lease Name or Unit Agreeme	ent Nam
			. OR TO DEEPEN OR F ERMIT" (FORM C-101)		State 'U' Gas Com	
PROPOSALS.) 	□ C W-11 □	Oil		8. Well Number 002	
2. Name of	Well: Oil Well	☑ Gas Well □	Otner:		9. OGRID Number	
Apache Corp					9. OGRID Number 873	
3. Address					10. Pool name or Wildcat	
303 Veterans	s Airpark Lane, Su	ite 3000 Midland,	TX 79705		Eunice Yates 7 Rivers Queen	
4. Well Loc	cation					
	it Letter_C		et from the North	line and 21	feet from the West	li
Sec	ction 32			Range 37E	NMPM County Lea	
		11. Elevatio	on (Show whether D	R, RKB, RT, GR, etc	(c.)	
	e de la companya de	3/05 NB			SALE TENENTS AND A	
	12 Cha	als Ammanniata	Day to Indicate	Noture of Notice	Damant on Other Date	
	12. Che	ск Арргориате	Dox to indicate	nature of Notice	e, Report or Other Data	
	NOTICE O	F INTENTION	TO:	l sui	BSEQUENT REPORT OF:	
PERFORM	REMEDIAL WORK	< ☐ PLUG AND	ABANDON 🗌	REMEDIAL WO	ORK ALTERING CA	ASING
TEMPORAF	RILY ABANDON	☐ CHANGE P	LANS	COMMENCE DI	RILLING OPNS. P AND A	
	LTER CASING	☐ MULTIPLE	COMPL [CASING/CEME	NT JOB 🔲	
DOWNHOL	E COMMINGLE	L		l l		
	E COMMININGLE	LJ		OTHER: TA		
OTHER:			ns (Clearly state al	OTHER: TA	and give pertinent dates including es	
OTHER:	cribe proposed or c	completed operation		l pertinent details, a	and give pertinent dates, including es Attach wellbore diagram of proposed	timated
OTHER: 13. Desc of st	cribe proposed or c	completed operation		l pertinent details, a	and give pertinent dates, including es Attach wellbore diagram of proposed	timated
OTHER: 13. Desc of st	cribe proposed or carting any propose	completed operation		l pertinent details, a		
OTHER: 13. Desc of st or re	cribe proposed or carting any propose completion.	completed operation	LE 1103. For Multi	l pertinent details, a		timated
OTHER: 13. Desc of st or re	eribe proposed or carting any propose ecompletion.	completed operation and work). SEE RU	LE 1103. For Multi	I pertinent details, a pertine	Attach wellbore diagram of proposed	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa	completed operation and work). SEE RU	LE 1103. For Multine following work: RIH & set CIBP @	I pertinent details, a iple Completions: A	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NM6	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but die	I pertinent details, a iple Completions: A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Attach wellbore diagram of proposed	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NM6	LE 1103. For Multine following work: RIH & set CIBP @	I pertinent details, a iple Completions: A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and status for 5 years.	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Pleas	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and status for 5 years.	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Pleas	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and status for 5 years.	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Pleas	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and status for 5 years.	I pertinent details, a iple Completions: A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	l comple
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and the set Status for 5 years.	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Pleas	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Tedonment Expir	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please S 2 5 4	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but dien and the set Status for 5 years.	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please S 2 5 4	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52	completed operation and work). SEE RUST all for this well, per the LD prod equipment 0# for 32 min. NMG	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Tedonment Expir	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please S 2 5 4	Attach wellbore diagram of proposed not on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52 Gonzales, he shoul	completed operation and work). SEE RUITED and for this well, per the LD prod equipment 0# for 32 min. NMG d be granting us TA Abance	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did a Status for 5 years. Approval of Tedonment Expiration. Rig Release I	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please 5 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Attach wellbore diagram of proposed int on top. Install wellhead flange; ran se find passing chart attached.	l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52 Gonzales, he shoul	completed operation and work). SEE RUITED and for this well, per the LD prod equipment 0# for 32 min. NMG d be granting us TA Abance	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did a Status for 5 years. Approval of Tedonment Expiration. Rig Release I	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please S 2 5 4	Attach wellbore diagram of proposed int on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewa MIRUSU POH & csg which held 52 Gonzales, he shoul	completed operation and work). SEE RUITED and for this well, per the LD prod equipment 0# for 32 min. NMG d be granting us TA Abance	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did a Status for 5 years. Approval of Tedonment Expiration. Rig Release I	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please 5 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Attach wellbore diagram of proposed int on top. Install wellhead flange; ran se find passing chart attached.	timated l compl
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52 Gonzales, he should be a control of that the information of the control of the contr	completed operation and work). SEE RUITED and for this well, per the LD prod equipment 0# for 32 min. NMG d be granting us TA Abance	LE 1103. For Multine following work: RIH & set CIBP @ OCD notified, but did a Status for 5 years. Approval of Tedonment Expiration. Rig Release I	I pertinent details, a iple Completions: A pertinent details, a pertinen	Attach wellbore diagram of proposed int on top. Install wellhead flange; ran se find passing chart attached.	chart c
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	eribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52 Gonzales, he should the should be	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please Solve S	Attach wellbore diagram of proposed on top. Install wellhead flange; ran se find passing chart attached. - 2016 JR. dge and belief. DATE 05/12/201	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C Spud Date: hereby certifications Fype or print	cribe proposed or carting any propose completion. equests TA renewal MIRUSU POH & csg which held 52 conzales, he should be consulted for the first the information of the consulted for the con	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A pertinent details, a pertinen	Attach wellbore diagram of proposed attach wellbore diagram of proposed attach wellbead flange; ran se find passing chart attached. - 2016 JR. DATE 05/12/201	timated I comple
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C	cribe proposed or carting any propose completion. equests TA renewal MIRUSU POH & csg which held 52 conzales, he should be consulted for the first the information of the consulted for the con	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please Solve S	Attach wellbore diagram of proposed on top. Install wellhead flange; ran se find passing chart attached. - 2016 JR. dge and belief. DATE 05/12/201 Dachecorp.com PHONE: 432/818	timated complete comp
OTHER: 13. Desc of st or re Apache re 5/6/2011 Per E.L. C Spud Date: hereby certifications Fype or print	cribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please Solve S	Attach wellbore diagram of proposed on top. Install wellhead flange; ran se find passing chart attached. - 2016 JR. dge and belief. DATE 05/12/201 Dachecorp.com PHONE: 432/818	timated complete comp
OTHER: 13. Desc of st or reserved. Apache results 5/6/2011 Per E.L. Company of the served of the served of the served. Signature of print for State Uses APPROVED	cribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG to be granting us TA Abanco	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please Solve S	Attach wellbore diagram of proposed on top. Install wellhead flange; ran se find passing chart attached. - 2016 JR. dge and belief. DATE 05/12/201	timated complete comp
OTHER: 13. Desc of st or reserved. Apache results 5/6/2011 Per E.L. Company of the served of the served of the served. Signature of print for State Uses APPROVED	eribe proposed or carting any propose ecompletion. equests TA renewal MIRUSU POH & csg which held 52 Gonzales, he should be a control of that the information of the control of the contr	completed operation and work). SEE RUITED prod equipment 0# for 32 min. NMG to be granting us TA Abanco	LE 1103. For Multi- the following work: The RIH & set CIBP @ OCD notified, but did A Status for 5 years. Approval of Te donment Expir Rig Release I and complete to the TITLE Sr. E	I pertinent details, a iple Completions: A 2950' w/35' cemer d not witness. Please Solve S	Attach wellbore diagram of proposed on top. Install wellhead flange; ran se find passing chart attached. - 2016 JR. dge and belief. DATE 05/12/201 Dachecorp.com PHONE: 432/818	timated complete comp

