	te all pertinent details, and give		
DTHER:		P, spot cmt plugs, run CIT, TA	
COMPLETION	CEMENT JOB		
PULL OR ALTER CASING 🔲 MULTIPLE		ABANDONMEN	ſ
PERFORM REMEDIAL WORK PLUG AND ABANDO			ING 🗌
NOTICE OF INTENTION TO:		BSEQUENT REPORT OF:	
12. Check Appropriate Box to I	ndicate Nature of Notice	Report or Other Data	
	ons, construct		
Pit type Depth to Groundwater Distance from ne Pit Liner Thickness: mil Below-Grade Tank:	varest fresh water well D		
Pit or Below-grade Tank Application or Closure			
	3114' GR		
11. Elevation (Show	25S Range 37E whether DR, RKB, RT, GR, e		ea [
Unit Letter K: 1650 feet from the	south line and	1650 feet from the west	line `
4. Well Location			
P.O. Box 50250 Midland, TX 79710-0250		Justis Devonian, North	
OXY USA Inc. 3. Address of Operator		16696 / 10. Pool name or Wildcat	
2. Name of Operator		9. OGRID Number	
Oil Well X Gas Well Other		5	
PROPOSALS.) 1. Type of Well:	,	8. Well Number	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FC		Hodges B	
SUNDRY NOTICES AND REPORTS (ON WELLS	7. Lease Name or Unit Agreement Na	ame:
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
District II 1625 N. French Dr., Hobbs, NM 8740555 OCD District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 84407 18 2011 1220 South St. Francis Dr. District IV Santa Fe, NM 87505		STATE FEE 🛛	-
		5. Indicate Type of Lease	
		WELL API NO. 30-025-11386	
1625 N. French Dr., Hobbs, NM 87249245	Office Energy, Minerals and Natural Resources		7, 2004
		Form	



HODGES B #5

05/02/2011

MI RUPU, Unhung head, POH w/ rods & pump LD, ndwh, nubop, POH w/ Tbg, BHA, RIH tag CIBP @ 7178, RIH w/ CIBP set @ 7100, Circulate the wellbore w/ Pkr fluid. SDWE.

05/03/2011

POH w/ Tubing & latch tool, RIH w/ Pkr test from surface to 3800 no leak found. SDON.

05/04/2011

located casing leak from 3844 to 3966, POH w/ tbg. SDON.

05/05/2011

POH w/ Kill string, RIH w/ wireline & tag @ 7100', run casing inspection log, sent to Midland for review, RIH w/ kill string. SDON.

05/06/2011

Contact NMOCD, rec verbal approval to set plugs, repair csg lk and TA well.

05/08/2011

RU HES set 25sx cement plugs @ 7100', 6450-6350', 5875-5775', 5175-5075', 4850-4750', pooh. RIH & set cmt retainer @ 3750', sqz 180sx cmt, Circulate to clean up, POH to 2500. SDON.

05/10/2011

POH w/ tbg, RIH w/ wireline bond log from 3640'-surface, sdon.

05/11/2011

RIH w/ Tbg, circulate pkr fluid, test csg, POH w/ Tbg. SDON.

05/12/2011

NDBOP, NUWH, Test casing. RD.



5/11-CR @ 3750'

5/11-25sx @ 4850-4750'

5/11-25sx @ 5175-5075'

5/11-25sx @ 5875-5775'

5/11-25sx @ 6450-6350'

5/11-CIBP @ 7100' w/ 25sx 2/11-CIBP @ 7178'

PBTD-7216'

TD-8500

4/62-25sx @ 8500-8425'