

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-06490

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Apache Corporation

3. Address of Operator
6120 S. Yale, Suite 1500, Tulsa, Oklahoma 74136-4224

4. Well Location
Unit Letter U : 990 Feet From The West Line and 990 Feet From The South Line

Section 2 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3471' GR

7. Lease Name or Unit Agreement Name

Northeast Drinkard Unit

8. Well No.
314

9. Pool name or Wildcat
Eunice Blinbry-Tubb-Drinkard-North

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-11-04 Set cmt. ret. 4200', sqz. 100 sx cmt. below ret. cap ret. w/ 5 sx.
2-12-04 Perforate @ 3198', set pkr. @ 2995', sqz. 50 sx cmt. thru perfs. WOC & tag @ 3070'.
2-16-04 Perforate @ 1400', set pkr. @ 1185' sqz. 50 sx cmt. thru perfs. WOC & tag @ 1304'.
2-16-04 Perforate @ 353', NU B-1 adapter flange. Sqz. 100 sx thru perfs. surface, out BH valve cmt. inside & out.
RDMO. Cut off wellhead, install dry hole marker, & clean location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 02/20/04

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (432) 530-0907

(This space for State Use)

APPROVED BY Hay W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 08 2004

CONDITIONS OF APPROVAL, IF ANY