Submit 3 Copies to Appropriate District Office State of	New Mexico	Form C-103
DISTRICT I Energy, Minerals a	and Natural Resources	Revised March 25, 1999
1025 N. French Dr., Hoods NM 88240	ATION DIVISION	WELL API NO. 30-025-36026
	St. Francis Dr.	5. Indicate Type of Lease
	Mexico 87504-2088	STATE X FEE
DISTRICT IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No. VO-5610
SUNDRY NOTICES AND REPORTS	ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1 PROPOSALS.)		
1. Type of Well:		Associate AZP State Com
Oil Well Gas Well X Other		/ toosolate / El Otate Com
2. Name of Operator	-	8. Well No.
Yates Petroleum Corporation 3. Address of Operator		9. Pool Name or Wildcat
105 South 4th Str., Artesia, N	NM 88210	Wildcat Morrow/Mississippian
4. Well Location		
Unit Letter :1650 feet from the South_	line and 2310	feet from the East line
Section 19 Township 15S Range	35E NMPM	County Lea
10. Elevation (Show whether DF, RKI 4028' GR	B, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice	e, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB]
OTHER:	OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompilation.	Approved as to	plugging of the Well Bore.
1-17-04 Reached TD of 12990' @ 6:00 a.m.	Liability under l	plugging of the Well Bore. Ond is retained until
1-19-04 to 1-20-04 Plugged well as follows: surface restoration is completed.		
Plug 1: 40 sx H w/additives 12956-12856	o'	
Plug 2: 50 sx H w/additives 11696-11596	6'	(A. 10)
Plug 3: 50 sx H w/additives 9680-9580'		/ Maria
Plug 4: 50 sx H w/additives 7318-7218'		
Plug 5: 45 sx C Neat 6090-5990'	0400 L. LO 47450	
Plug 6: 40 sx C w/additives 4727-4627'		Hobbs ED
Plug 7: 40 sx C w/additives 4715-4615'	(WOC and tagged @ 4630')	000 OCD
Plug 8: 25 sx C w/additives 1938-1838' Plug 9: 25 sx C Neat 430-330'		Ten O
Plug 10: 25 sx C Neat 430-330 Plug 10: 25 sx C Neat 30' to surface.		92420271 303
WELL IS PLUGGED & ABANDONED. FINAL REPORT.		
Thereby certify that the information attove a true and complete to the best of my knowledge and belief.		
SIGNATURE Storm Louis TITLE		nician DATE 1/28/04
Type or print name Stormi Davis		Telephone No. 505-748-1471
(This space for State use)		
APPROVED BY TITLE		DATE MAD O O OOO
Conditions of approval, if any:	PETROLEUM ENGINEE	