

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

RECEIVED
JUN 02 2011
HOBBS CO
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26307
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ Brine Well		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Buckeye Disposal LLC		6. State Oil & Gas Lease No.
3. Address of Operator 2416 Erskine Lubbock TX 79408		7. Lease Name or Unit Agreement Name Salt Dog Brine Supply Well
4. Well Location Unit Letter J : 1980 feet from the South line and 1980 feet from the East line Section 5 Township 19S Range 36E NMPM County Lea		8. Well Number Brine Well Supply #1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number
		10. Pool name or Wildcat BSW - Salado

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

~~Spud Date~~ Rig Up Pulling Unit
Come out of hole with tubing
Attach Drilling Bit (size 2 3/8) drill to a
depth of 2600 Ft.
Come out of hole with work string
Run packer to test Casing.
Go back in hole with tubing
Rig Down Pulling Unit.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Wallace TITLE Manager DATE 5-18-11

Type or print name Terry Wallace E-mail address: terryw@the standard energy. com PHONE: 525-390-6167
For State Use Only

APPROVED BY: [Signature] TITLE State MGR DATE 6-2-2011
Conditions of Approval (if any):