

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505


Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-34622
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: Arco Hall State
4. Well Location Unit Letter <u>K</u> : 1980 feet from the <u>South</u> line and 1980 feet from the <u>West</u> line Section <u>20</u> Township <u>20S</u> Range <u>36E</u> NMPM Lea County		8. Well No. <u>3</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3633' GR		9. Pool name or Wildcat Eumont Y-SR-Q

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU Pulling Unit.
- 2) Spot 25 sx @3880' & tag.
- 3) Circulate hole w/9.5# mud.
- 4) Spot 25 sx @ 2000' & tag.
- 5) Spot 25 sx @ 415'.
- 6) Spot 5 sx from 50'.
- 7) Install dry hole marker & clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 3/2/04
Type or print name ACrawford@xericoil.com 432-683-3171
(This space for State use) Telephone No.

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 10 2004
Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: Arco Hall #3

API# 30-025-34622

COUNTY: Lea

STATE: NM

HOLE SIZE: 11"
CASING: 8 5/8" @ 413'
CEMENTED WITH: 260 SX
CEMENT TOP: Surf.

TUBING: B37 1/2" @ 3885'

RODS: _____

PUMP: _____

PACKER: _____

PERFS:
3888' - 3926'
3988' - 96'
4060' - 75'

HOLE SIZE: 7 7/8"
CASING: 5 1/2" @ 4249'
CEMENTED WITH: 950 SX
CEMENT TOP: Surf.

PBTD: 4210'

TD: 4250'