New Mexico Gil C

☐ Final Abandonment Notice

Form 3160-5 (August 1999)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMLC032573A		
			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well				7. If Unit or CA/Agreement, Name and/or No.	
☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No.	
2. Name of Operator SAGA PETROLEUM LLC				E M Elliott Fed #3 9. API Well No.	
3a. Address		3b. Phone No. (inclu	de area code)	30-025-10398	
415 W. WALL, SUITE 190 4. Location of Well (Footage, S	ec., T., R., M., or Survey Descriptio	(432)684-4293		10. Field and Pool, or Exploratory Area Tubbs - BLinebry Oil & Gas	
510' FNL & 2130' FWL Sec. 22 (C), T22S, R37E				11. County or Parish, State Lea NM	
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION					
□ Notice of Intent □ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	□ Deepen□ Fracture Treat□ New Construction	☐ Production (Star ☐ Reclamation ☐ Recomplete	t/ Resume) ☐ Water Shut-Off ☐ Well Integrity ☑ Other DHC Blinebry &	

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

☐ Plug Back

Temporarily Abandon

Water Disposal

Tubb perfs

3-02-04 MIRU PU, unhang well, LDPR, POOH w/rods & pump, NDWH, NU BOP, release TAC, TOOH w/tbg. 3-03-04 PU & RIH w/retrieving head, TIH to RBP, attempt to wash balls off plug, run out of wtr, wait on wtr, continue to wash balls, catch plug, release plug. POOH w/tbg & plug

3-04-04 RU Phils Testers, hydrotest 2-3/8" tbg to 5000 psi below slips, no failures, land tbg, ND BOP, set TAC w/46K tension, NUWH, PU & RIH w/pump & rods, change 34- 3/4" rod boxes & 11- 7/8" boxes. Hang on, space out, load & feet tog & pump action to 500 psi - both test good. 1-26' 1-1/4" PR. 77-1925' 7/8" sucker rods. 184-4600' 3/4" sucker rods. 12-300' 7/8" sucker rods. 1-20' -20-125-RHBC-20-6 pump. 172 jts 2-3/8" 4.6# J-55 EUE 8rd tbg. 1-2.8/2-3/8"

46 jts 2-3/8" 4.6# J-55 EUE 8rd tbg. 1-4' 2-3/8" perf sub. 1-31' 2-3/8" BPMA

Change Plans

Convert to Injection

DHC Tubb perfs 5964'-6142' & Blinebry perfs 5481'-5654' by Order No. HOB-0078 dated 2-24-04 Production to be allocated - Blinebry Oil 16%, Wtr 95%, Gas 14% & Tubb Oil 84%, Wtr 5%, Gas 86%

I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Bonnie Husband **Production Analyst** Signature Date 03/08/2004 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Conditions of approval Aff any, 2 re 2004 bed. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 Prnakes ibascrime for any person knowingly and willfully to fraudulent statements or representations as for any matter within its jurisdiction.

Well Completion Report (Form 3160-4) for the Blinebry recompletion must be filed before we can enter this well as subsurface commingled from the Blinebry Oil and Gas Pool and the Tubb Oil and Gas Pool.

(Instructions on reverse)

