

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-04760

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Harry Leonard NCT-A

8. Well No.

7

9. Pool name or Wildcat

Eumont, Yates, 7 Rvrs, Queen

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Chevron USA Inc

3. Address of Operator

15 Smith Rd, Midland, TX, 79705

4. Well Location

Unit Letter M : 660 feet from the South line and 660 feet from the West line

Section 22 Township 21-S Range 36-E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: Replug ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2 CIBP at 3030, spot 25sx, plug from 3030-2800 (Eumont), Tag at 2779.
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
3. Perf 4 holes at 2700, unable to sqz, spot 30sx, plug from 2750-2500 (B-Salt), Tag at 2421.
4. Perf 4 holes at 1400, sqz w/60sx from 1400-1200, Tag at 1404, re-sqz, perf w/100sx (T-Salt), Tag at 1107.
5. Perf 4 holes at 450, Circ cmt 5 1/2 x 8 5/8 csg from 450-Surf w/200sx (8 5/8 Shoe), Tag at Surf.
6. Install dry hole marker 2-24-04.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Manager/Sunset

DATE 2/24/04

Type or print name Jimmy Bagley

(This space for State use)

Telephone No. (432) 561-8600

APPROVED BY

TITLE FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

Conditions of approval, if any

