## NEW MEXICO OIL CONSERVATION COMMISSION//Oba

	NEW MEXICO OIL CONSERVATION	COMMISSION CARRE	
	Santa Fe, New Mexico MISCELLANEOUS NO	TICES 1958 APR 10	E OCC
Submit this notice in TRIPLICAT returned to the sender on which or agent, of the plan submitted. I	E to the District Office, Oil Conservation Commission will be given the approval, with any modifications of the plan as approved should be followed, and work d Regulations of the Commission.	on, before the work specified is to begin	the Commission
	Indicate Nature of Notice by Checkin	ng Below	
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	

Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	X	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
Notice of Intention		Notice of Intention	Notice of Intention	
TO GUN PERFORATE  OIL CONSERVATION COMM SANTA FE, NEW MEXICO  Gentlemen:		Hobbs, New Hexic	(OTHER)  April 6, 1956 (Date)	
TO GUN PERFORATE  OIL CONSERVATION COMM SANTA FE, NEW MEXICO  Gentlemen:  Following is a Notice of In	itention to de	Hobbs, New Hexic  (Place)  Description of the control of the contr	(Other)  April 6, 1956 (Date)	
TO GUN PERFORATE  OIL CONSERVATION COMM SANTA FE, NEW MEXICO  Gentlemen:  Following is a Notice of In  (Compa	itention to do	Hobbs, New Hexic (Place)  concertain work as described below at the	(OTHER)  April 6, 1956 (Date)  A. R. Skarda  Well No. 1	(Unit)
TO GUN PERFORATE  OIL CONSERVATION COMMISANTA FE, NEW MEXICO  Gentlemen:  Following is a Notice of In  (Compa	itention to do	Hobbs, New Hexic (Place)  c certain work as described below at the.	(OTHER)  April 6, 1956 (Date)  A. R. Skarda  Well No. 1	(Unit)
TO GUN PERFORATE  OIL CONSERVATION COMM SANTA FE, NEW MEXICO  Gentlemen:  Following is a Notice of In  (Compa	Jackson In or Operator Sec. 3	Hobbs, New Hexic  Control (Place)  Contr	(OTHER)  April 6, 1956 (Date)  A. R. Skarda  Well No. 1	(Unit)

be shot off at approximately 2200/ The casing will be laid down and tubing will be returned to stub and a 25 sx cement plug will be placed at this point. A 15 sack plug will be run at 1500', a 10 sack plug will be run at bottom of surface and a 5 sack top hole plug with a 10' marker 5' above the ground.

provedept as follows:	Company or Operator
roved CONSERVATION COMMISSION	By Curtweel  Position Agent  Send Communications regarding well to:
CONSERVATION COMMISSION	F. R. Jackson, Oil Operator
е	Address P. O. Box 147 Longview, Tex. Attn: Mr. Bill Baird