

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
ILE		
.S.G.S.		
AND OFFICE		
PERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Disposal Well		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
Name of Operator Sage Energy Company		5. State Oil & Gas Lease No. E 9713
Address of Operator P.O. Drawer 3068, Midland, Texas 79702		7. Unit Agreement Name
Location of Well UNIT LETTER <u>A</u> , <u>510</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM.		8. Farm or Lease Name No Pit Pete SWD
15. Elevation (Show whether DF, RT, GR, etc.) NA		9. Well No. 1
12. County Lea		10. Field and Pool, or Wildcat

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REFORM REMEDIAL WORK <input type="checkbox"/> MPROVARI ABANDON <input type="checkbox"/> LL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JQB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
---	--	---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set retainer at 10,591', pumped 200 sx Class "H", displaced to the perms.  
Circulated hole with 10#'s Gel Brine.

Spot 10 sx plug at 7519'  
Perf. 1 hole at 3500'  
Pumped 10 sx. plug, shot hole at 2100',  
Pumped 10 sx plug.  
Pumped 10 sx plug at 1650'  
Pumped 10 sx plug at 358'  
Pumped 10 sx plug at surface. Set P&A marker.

Witnessed by State Represenative

No pipe recovered.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

PROD BY <u>Francis Holguet</u>	TITLE <u>Production Clerk</u>	DATE <u>June 27, 1985</u>
PROD BY <u>Dussard</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>MAR 14 1988</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 28 1985

003  
HOBBS OFFICE