

| | | |
|---------------------|--|--|
| NO. COPIES RECEIVED | | |
| DISTRIBUTION | | |
| LANTA FE | | |
| FILE | | |
| U.S.D.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator The Wil-Mc Oil Corporation | 8. Farm or Lease Name White State |
| 3. Address of Operator Drawer 1889, Midland, Texas 79701 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER A, 660 FEET FROM THE East LINE AND 660 FEET FROM THE North LINE, SECTION 15 TOWNSHIP 10S RANGE 32S NMPM. | 10. Field and Pool, or Wildcat N. Mescalero Wolf |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4328' Gr. | 12. County Lea |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP at 8500' and dumped 4 sacks cement on top of plug.
- Shot off 4 1/2" casing at 3440' and layed down casing.
- Ran 2 3/8" tubing to 3481' and displaced hole with 25 lbs./bbl. mud to 4 1/2" casing stub.
- Spotted 100' cement plug over 4 1/2" casing stub at 3440'.
- Pulled 2 3/8" tubing to 1600', displaced hole with mud and spotted 100' cement plug.
- Pulled 2 3/8" tubing to 352', displaced hole with mud and spotted 100' cement plug over surface pipe shoe.
- Pulled 2 3/8" tubing, finished displacing hole with mud and capped with 10 sacks cement plug.
- Installed marker, cleaned and leveled location.

Note: 8 5/8" intermediate casing left in hole - set at 3516'.
Work completed 10-19-73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED JM Kelgatch TITLE Engineer DATE 10-29-73

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: