

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

FEB 10 11 25 AM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>9943</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Cities Service Oil Company</b>		8. Farm or Lease Name <b>State AD</b>
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>		9. Well No. <b>#4</b>
4. Location of Well UNIT LETTER <b>0</b> <b>329</b> FEET FROM THE <b>South</b> LINE AND <b>2315</b> FEET FROM THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>10S</b> RANGE <b>32E</b> NMPM.		10. Field and Pool, or Wildcat <b>Mescalero Permo Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4345 DF</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged in the following manner:

1. Cement retainer set at 8160'. Displaced 240 sx cement below retainer and 10 sax on top of retainer from 8160 to 8080'.
2. Cut off 5½" casing at 4050'. Displaced 50 sack cement plug ½ in - ½ out of 5½" stub from 4130' to 3920'. Recovered approximately 4050' of 5½" casing.
3. Displaced 50 sack cement plug ½ in - ½ out of 8 5/8" casing from 3510 to 3360'.
4. Put 10 sack plug in top of 8 5/8" casing from bottom cellar to 30' and installed 4" pipe marker.
5. Prepare to clean location of all equipment, debris and fill mud pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **District Clerk** DATE **February 9, 1967**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: