

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
E-1110

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name ---
Name of Operator MORRIS R. ANTWEIL		8. Farm or Lease Name New Mexico "AF" State
Address of Operator P. O. Box 2010, Hobbs, NM 88240		9. Well No. 2
Location of Well UNIT LETTER I, 2310 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 10-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Mescalero Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4337' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed to P&A as follows with tubing & rod fish in hole:

1. Run cement retainer. Set @ 5122'. Squeeze below retainer with 225 sx Cement having 15 sx cement on top of retainer.
2. Cut & pull an estimated 4000' 5½" casing.
3. Spot 45 sx cement plug on 5½" casing stub. (Circulated 9-5/8" casing is set @ 4241'.
4. Spot 45 sx cement plug across 13-3/8" casing shoe @ 486'.
5. Spot 10 sx surface plug w/marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. M. Williams</u>	TITLE <u>Agent</u>	DATE <u>25 March 82</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT 1 SUPR.</u>	TITLE _____	DATE <u>MAR 29 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

MAR 26 1982

O.C.D.  
HOBBS OFFICE