

COPIES RECEIVED		
TRIBUTION		
FAFE		
E		
S.G.S.		
AND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-9596

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State M "A"
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 11-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat Moore - Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4341' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Pullers, Inc. set Cast Iron Bridge Plug at 8130' with 4 sx. cement plug on top from 8130' to 8095'. Shot and pulled 5-1/2" casing from 4014'. Spotted 76 sx. cement plug from 3714' to 4064' and 35 sx. cement plug from 3410' to 3510'. Cut and pulled 8-5/8" casing from 82'. Spotted 136 sx. cement plug from 300' to surface. Spotted 10 sx. cement plug with dry hole marker. Circulated brine water mud between plugs.
Well P&A 5-14-74

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED MP Black TITLE Supvr., Admin. Services DATE 5-21-74

APPROVED BY John W. Penney TITLE Secretary DATE
CONDITIONS OF APPROVAL, IF ANY: