

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>P &amp; A</b>	7. Unit Agreement Name
2. Name of Operator <b>Samedan Oil Corporation</b>	8. Farm or Lease Name <b>John H. Moore "B"</b>
3. Address of Operator <b>900 Wall Towers East, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>E</b> , <b>1650</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>West</b> LINE, SECTION <b>25</b> TOWNSHIP <b>11-S</b> RANGE <b>32-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Moore Dev./Permo Penn.</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4338' GL</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**P&A as follows:**

Set CIBP at 9810' w/20' cement on top  
Set CIBP at 8161' w/20' cement on top  
Pull 4697' of 7" casing  
Set 60 ex. cement plug 4750' (tagged plug at 4597')  
Set 60 ex. cement plug 3525' (tagged plug at 3427')  
Set 50 ex. cement plug 1400'  
Pull 9 5/8" casing 350'  
Set 100 ex. cement plug at 400' (tagged plug at 170')  
Set 10 ex. plug at surface  
Installed DHM, location levelled and cleared of junk per rule 202. Operations comp.  
Jan. 23, 1978. NMOCC representative present to witness plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Alan Bump **Alan Bump** TITLE **Division Clerk** DATE **July 6, 1978**  
APPROVED BY Eddie Seay TITLE **OIL & GAS INSPECTOR** DATE **MAR 14 1980**  
CONDITIONS OF APPROVAL, IF ANY: