SANTA FE	NEW MEXICO OIL CONSERVATION COMMISS	Form C-103 Supersedes Old C-102 and C-103
U.S.G.S.	1	Effective 1-1-65
LAND OFFICE	30-025-00098	5a. Indicate Type of Lease
OPERATOR		State Fee X
CIMID		5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROP USE "APPLICATION	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
WELL WELL	•	7. Unit Agreement Name
2. Name of Operator	other Salt Water Disposal	8. Farm or Lease Name
3. Address of Operator	Amerada Hess Corporation 3. Address of Operator	
Drawer D, Monument, NM 88265		East Caprock S.W.D.
UNIT LETTERI 660) FEET FROM THE East LINE AND 1980 FEET FR	10. Field and Pool, or Wildcat
South	FEET FROM THE LAST LINE AND TEET FR	East Caprock
THE SOULII LINE, SECTION	TOWNSHIP IZ J. BANGE 32 E	
	15. Elevation (Show whether DF, RT, GR, etc.)	
16.	7/// 433/ DF	12. County Lea
Check Ap NOTICE OF INT	propriate Box To Indicate Nature of Notice, Report or C	Other Date
	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	ALTERING CASING
	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	OTHER	
17. Describe Proposed or Completed Operat work) SEE RULE 1103.	tions (Clearly state all pertinent details, and give pertinent dates, including	
	dates, including the pertinent dates, including	g estimated date of starting any proposed
Sentembon 1077	•	
Ran 2-3/8" tbg t	0 3663" and circulated hold at	. •
found no coment	o 3663' and circulated hole clean w/p ass H cement. Pulled tbg WOC and ran Pulled tbg up to 3663' and pumped 10	roduced water and
ment Pulled +	balled the up to 3663' and numbed 10	the country and
W/210 bbls 10 54	by wot and checked top of cement at 20	1121 SKS Class H ce-
cement mixed w/2	% CaCl and circulated cement out of 13 1 head and spotted 10 sks cement in to	100 sks class H
installed the	% call and circulated cement out of 13 head and spotted 10 sks cement in to le marker. Plugging procedure verball	3-3/8" csg. Pulled
Saxton w/New Mey	l nead and spotted 10 sks cement in to le marker. Plugging procedure verball conservation Commission and wi	p of 8-5/8" csg.
w/New Mexico Oil	re marker. Plugging procedure verball ico Oil Conservation Commission and wi Conservation Commission.	y approved by Jerry
	commission.	onessed by W. Clegg.
18. I hereby certify that the information		
the information above	is true and complete to the best of my knowledge and belief.	
SIGNED ES SILVE		
	TITLE Supv. Admin. Serv.	DATE 11-3-77
APPROVED BY Willita.	OH & CAC DO	r WOW
CONDITIONS OF APPROVAL, IF ANY:	OU & GAS INSDECTOR	DATE
	,	
•		