	we. OF EDFICE ACCIVES					-		
	DISTRIBUTION			T	1			
	SANTA PE			1				
	PILE			1	ĺ			
	U.S.G.S.				AU	ΥIJ		
	LAND OFFICE		1		^0			
	INANSPORTER	OIL	1					
		GAS						
į	OPERATOR							
	PROHATION OFFICE							
1	Operator							
	Amerada Hess Corporation							
	Address							
	P. O. Boy 591 Midland T							

NEW MEXICO OIL CONSERVATION COMMISSION REQUEST FOR ALLOWABLE AND

Form C-104 Supersedes Old C-104 and C Elfective 1-1-65

IORIZATION TO TRANSPORT OIL AND NATURAL GAS

	EARD OFFICE	_			••••				
	THANSPORTER OIL	- 			•				
	OPERATOR GAS	4							
ı.	PROBATION OFFICE								
••	Operator					·			
	Amerada Hess Cor			•					
			•						
	P. O. Box 591. M Reason(s) for tiling (Check proper bo	idland, Texas 79701	Joil to						
	New Well	Change in Transporter of:	Other (Please	e explorinj	CHANGE NAME AMERADA D	FROM			
	Recompletion	OII Dry	Gas [AMERADA HESS COR	PORATION			
	Change in Ow ership	Casinghead Gas Cond	lensate		TO AMERADA HESS CO	ORFORATION 1. 1971			
	If change o, ownership give name		6		EFFECTIVE MOST				
	and address of previous owner			·					
п.	DESCRIPTION OF WELL AND	LEASE							
	Lease Name	Well No. Pool Name, Including	Formation	Kendirol Leas		Lease No			
	H. C. Posey "A"	3 East Caprock	-Devonian	States, Federa	lor Fee Fee				
•	Location				.,				
	Unit Letter J : 1980	Feet From The South L	ine and <u>1980*</u>	_ Eisent From '	rh• <u>East</u>				
	Line of Section 11 To	wnship 12_S Range 3	2_E • , NMPM	,	. Т.	_			
			C-L , temper		Lea	County			
П.	DESIGNATION OF TRANSPOR	TER OF OIL AND NATURAL G							
	Name of Authorized Transporter of Oil Amogo	or Condensate	Address (Give address &						
•	Name of Authorized Transporter of Ca	singhead Gas or Dry Gas	3411 Knoxvil Address (Give address a	<u>le AveI</u>	ubbo c k, Texas	79413			
	None		11000 (0100 000)233 2	o winners appro-	rea copy of this form is	to be sent;			
	If well produces oil or liquids,	Unit Sec. Twp. P.qe.	Is gas actually connecte	d? Whe	en .	······································			
	give location of tanks.	; J :11 :12-S:32-E							
••	If this production is commingled wi	th that from any other lease or pool	, give commingling order	number:		•			
٧.	COMPLETION DATA	Oil Well Gas Well	New Well Workover	Desepen	True para la comp	. 1577			
	Designate Type of Completic	on – (X)	, and and a moreover	i i	Plug Back Same Re	s'v. Diff. Res			
	Date Spudded	Date Compl. Ready to Prod.	Total Depth		P.B.T.D.	i			
	Elevations (DF, RKB, RT, GR, etc.)	Name of Producing Formation	Top Oil/Gas Pay		Tubing Depth				
	Perforations			· ·	Depth Casing Shoe				
		•			Depth Cesting Shoe				
ļ		TUBING, CASING, AN	D CEMENTING RECORT)	1				
	HOLE SIZE	CASING & TUBING SIZE	DEPTH SE		SACKS CER	MENT			
			1		ļ				
y.`	TEST DATA AND REQUEST FO	OR ALLOWABLE (Test must be a	after recovery of total volum	u of žwad oll e	and must be sound to or	exceed too alli			
ï	II, WELL able for this depth or be for full 24 hours)								
-	Date First New Off Mun 10 lanks	Date of Test	Producing Method (Flow,	pumini gas lij	i, eic.)				
ł	Length of Test	Tubing Pressure	Casing Pressure		Choke Size				
				•					
	Actual Prod. During Test	Oil-Bble.	Water-Bble.		Gde-MCF				
Į									
	GAS WELL								
Γ	Actual Frod. Teet-MCF/D	Length of Test	Bbie. Condensate/MMCF		Gravity of Condensate				
ſ	Testing Method (pitot, back pr.)	Tubing Pressure (Shat-in)	Casing Pressure (Shut-	(a)	Choke Size				
_ L			<u> </u>		<u> </u>				
I. (CERTIFICATE OF COMPLIANO	E "	OIL C	ONSTERVA	TION COMMISSIO	N			
•	hereby certify that the rules and re	emiletines of the Oil Consequetion	APPROVED A	UG 128 1	971	19			
(Commission have been compiled w	ith and that the information given	ho the						
. •	bove is true and complete to the	best of my knowledge and belief.	BY		TI I	**************************************			
	O . O		TITLE		This I	to the second			
	Millriner		This form is to	be familed in c	ompliance with RUL	E 1104.			
-	والمناور		If this is a request face allowable for a newly drilled or deeper- well, this form must be semecompanied by a labulation of the deviation tages taken on the well man accordance with RULE 111.						
	PRODUCTION THE	CURDS SUPERVISOR							
-	Tu	4)	All sections of	his tarm mu	it be filled out compl	etaly for allu-			
.	entra transfer som skipped til		in any and the second	m					
	· · · · · · · · · · · · · · · · · · ·			The f	, · · · · · · · · · · · · · · · · · · ·				

RECEIVED

AUS 1 1971

OL CONSERVATION COMM.