NO. OF COPIES RECE	IVED										
DISTRIBUTION			NEW MEXICO OIL CONSERVATION COMMISSION								
SANTA FE			NEW MEXICO OIL CONSERVATION COMMISSION						Form C-101		
FILE									Revised 1-1-		
U.S.G.S.										e Type of Lease	
LAND OFFICE									STATE		
OPERATOR									5. State Oil	& Gas Lease No.	
.APF	LICATIC	N FOR	PERMIT	TO DRIL		, OR PLUG	PACK		$\chi$		
1a. Type of Work				TO BRIE		, OK FLUG	DACK				
	<b>DDU</b> 1	1			<b></b>				7. Unit Agre	eement Name	
b. Type of Well		1		DEEP	EN		PLUC	З ВАСК 🚺			
OIL X	GAS WELL	}	OTHER			SINGLE	м	ULTIPLE	8. Farm or 1	Lease Name	
2. Name of Operator			OTHER			ZONE		ZONE	State	<u>EC "C"</u>	
Amerada Hes	ss Corp	orati	on						9. Well No.		
3. Address of Operator							2				
Drawer D, 1	Monumen	t. Ne	w Mexico	88265					10, Field and Pool, or Wildcat		
4. Location of Well								East Caprock-Wolfcamp			
	UNIT LETT	ER		LOCATED	1900	FEET FROM THE	East	t	$\Lambda M M$		
AND 660'	FEET FROM	THE	North		. 11	120		205	$\chi$		
<u>uuuuuuu</u>		1111	mm	LINE OF SE	iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	тwp. 12S	RGE.	32E NMPM	$\overline{\gamma}\overline{\eta}\overline{\eta}$		
())))))))))))))))))))))))))))))))))))))	111111	IIII		111111.					12. County		
<i></i>	HHH	HHH	HHHH	ннн	<i>+++++++</i> +	*******	<i>HHH</i>	<u>ttttttt</u>	Lea		
		/////	///////						IIIIII		
<i>{}}}}}</i>	HHHH	HHH	******	HHH	<i>HHHHH</i>		TITT		$\overline{\Pi}$		
AIIIIIIIIIII	//////			illilli.		19, Proposed I	Jepth	19A. Formatio	n	20. Rotary or C.T.	
21. Elevations (Show	whether DF	RT. etc			18 Plug. Bond			<u> </u>		Pulling Unit	
4356' DF		,		lanket	is ring. Bond	21B. Drilling (	Contractor		22. Approx	x. Date Work will start	
23.		<b></b>				L			10-1	5-87	
				PROPOS		ND CEMENT P					

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CRUT	
17-1/2"	13-3/8"	35,6#	297'	225	
12-1/4"	8-5/8"	32 & 24#	3,585'	1,500	<u>Circ.</u> 1,058'
11"	5-1/2"	20 & 17#	11,155'	600	8,603'
			1	8	

Plan to MIRU pulling unit, install BOP & TIH w/bit to 10,979'. Recover bit & run GR-CCL-CNL log fr. 10,979' to 8000'. Run CIBP on wireline set at 10,930' & dump 35' cement on top of CIBP. Test plug to 3000#. Abandon Devonian Zone. Perforate 5-1/2" csg. at 8300' w/4SPF, establish inj. rate into perfs & squeeze w/100 sks. Class H neat cement. WOC. Run bit, dril out squeeze, & test. Perforate Wolfcamp Zone 5-1/2" csg. fr. 8390' to 8406' w/2SPF. Acidize new perfs. w/1000 gal. 15% NEFE acid if necessary. Swab load & place well on

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE AND PROPOSED NEW

I nereby certify that the information above is true and con	plete to the best of my knowledge and belief.	
Signed K. Wheele, fe	TüleSupv. Adm. Svc	Date 10-14-87
(This space for State Use)		

ORIGINAL SIGNED BY JERRY SEXTON APPROVED BY \_\_\_\_\_\_ DISTRICT I SUPERVISOR \_\_\_\_\_ TITLE \_ CONDITIONS OF APPROVAL, IF ANY: OCT 1 5 1987

Permit Expires 6 Menths From Approvat Date Unloss Drilling Underway