

COPY

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5c. Indicate Type of Lease
State ☐ Free ☒
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL ☐ GAS WELL ☐ OTHER- Injection well	7. Unit Agreement Name
2. Name of Operator	NE Caprock Queen Unit
MURPHY OPERATING CORPORATION	8. Farm or Lease Name
3. Address of Operator	NE Caprock Queen Unit
P. O. Drawer 2648, Roswell, New Mexico 88201	9. Well No.
4. Location of Well	34 0
UNIT LETTER L 230 660 FEET FROM THE West 2310 1980 FEET FROM	10. Field and Pool, or Wildcat
THE South LINE, SECTION 21 TOWNSHIP 12 South RANGE 32 East NMPM.	Caprock Queen
15. Elevation (Show whether DF, FT, GR, etc.)	12. County
4369' DF	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDON/CENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-1-85 Pumped out flow lines & loaded tbgs.
4-2-85 Pumped out injection line.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Louis N. Brown TITLE Production Records DATE May 17, 1985

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

MAY 21 1985

COPY

orig + xc to Artesia
CCD.