

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-00159

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-9946

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Lease Name or Unit Agreement Name Northeast Caprock Queen Unit
2. Name of Operator Murphy Operating Corporation		8. Well No. 24
3. Address of Operator P.O. Drawer 2648, Roswell, New Mexico 88202-2648		9. Pool name or Wildcat Caprock Queen
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>12 South</u> Range <u>32 East</u> NMPM Lea County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4356' DF		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned in the following manner:

08/24/93: Set Plug #1 from 2915' to 2685' (230') with 150 sacks Class H with 1% CaCL.

08/25/93: Displace with 210 bbls salt water gel at 25#/bbl. Perforate at 310'. Set Plug #2 from 315' to 184' (116') with 100 sacks Class H with 2% CaCL. Set Plug #3 at Surface with 20 sacks Class H. Install dry hole marker.

Prep to fill pit, cut off deadman and remove fencing for finalization.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Garcia TITLE Production Records Manager DATE 9/14/93

TYPE OR PRINT NAME Carol J. Garcia TELEPHONE NO. (505)622-1127

(This space for State Use)

APPROVED BY Jack Griffin OIL & GAS INSPECTOR DATE NOV 02 1993

CONDITIONS OF APPROVAL, IF ANY:

SAD