

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-00164
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator WAGNER & BROWN		6. State Oil & Gas Lease No. K-3920
3. Address of Operator P.O. Box 1714, Midland, TX 79702		7. Lease Name or Unit Agreement Name CLEVELAND
4. Well Location Unit Letter <u>G</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>23</u> Township <u>12S</u> Range <u>32E</u> NMPM Lea County		8. Well No. 1-23
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4342' DF		9. Pool name or Wildcat East Caprock Devonian

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. *(Tanks being sold, and date to be initiated)*

- 1) Set CIBP @ 9000' topped with 35 ft (5 sx), Class "C" on top
- 2) Displaced hole w/ 10 ppg mud and spotted cement plugs as follows:
@ 6400' w/ 25 sx
@ 5050' w/ 25 sx
@ 4350' w/ 35 sx

- 3) Cut 5-1/2" csg @ 3850' and POOH. Spotted cmt plug 3900-3590' w/ 80sx and tag
- 4) Sptd cmt plug in 8-5/8" csg 1100'-1000' w/ 35 sx.
- 5) Sptd cmt plug in 8-5/8" csg from 375'-275' w/ 35sx and tagged.

6) Sptd 10 sx plug @ surface, welded on plate and installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Drew Diggins TITLE Engineer DATE 5/12/89

TYPE OR PRINT NAME Drew Diggins

TELEPHONE NO. (915) 686-598

(This space for State Use)

APPROVED BY R.A. Sadler TITLE OIL & GAS INSPECTOR DATE AUG 16 1989

CONDITIONS OF APPROVAL, IF ANY:

R B

RECEIVED

MAY 17 1969

**OCD
HOBBS OFFICE**