

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9946	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection</u>	7. Unit Agreement Name <u>Northeast Caprock Queen Unit</u>
2. Name of Operator <u>MR Oil Company</u>	8. Farm or Lease Name <u>Noetheast Caprock Queen Unit</u>
3. Address of Operator <u>Box 685, Monahans, Texas 79756</u>	9. Well No. <u>26</u>
4. Location of Well UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>12S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat <u>Caprock Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4339 DF</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <u>Temporary Abandon</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/1/84 Set cast iron B.P. @ 2934'.
10/2/84 Circulate hole through tbg w/10# mud.
10/2/84 Spot 15 sks cement on top of B.P.
10/2/84 Test casing to 500 psi.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Bill Myszura</u>	TITLE <u>Consultant</u>	DATE <u>10/18/84</u>
APPROVED BY <u>Eddie W. Seay</u> <u>Oil & Gas Inspector</u>		DATE <u>OCT 22 1984</u>
CONDITIONS OF APPROVAL, IF ANY: <u>Expires 10/22/85</u>		

RECEIVED

OCT 19 1984

O.C.D.
HOSES OFFICE