NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

DECORPORATION AND AUG 7 1844

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission

REPORT ON BEGINNING DRIL	LING OPERATIONS	REPORT ON REPAIRING WELL	***
REPORT ON RESULT OF SHOOTREATMENT OF WELL	OTING OR CHEMICAL	REPORT ON PULLING OR OTHER ALTERING CASING	WISE
REPORT ON RESULT OF TEST SHUT-OFF	OF CASING	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLU	JGGING OF WELL		
	Taibho	ock, Texas 7-31-44	1
		Place	Date
OIL CONSERVATION CON Santa Fe, New Mexico. Gentlemen:	MMISSION		
Fellowing is a report on the	work done and the resul	ts obtained under the heading noted a	above at the
Malco Refineries	or Operator	Lease Well No.	in the
		.т. 12-S , R. 32-1	
G-prook	Field,	Lea-	County
The dates of this work we	re as follows:	7-30-44	•
Squeezed at 1380. Took	ed plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 $700_7^{\#}$ to start an	omitted on Form C-102 on tained. (Cross out incorrect words.) RK DONE AND RESULTS OBTAIN O sacks cement through dobtained good circular Pumped plug down to 136	IED perforations tion through
Squeezed at 1380. Took bradenhead with	ed plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 $700_7^{\#}$ to start an	tained. (Cross out incorrect words.) RK DONE AND RESULTS OBTAIN O sacks cement through d obtained good circuls	IED perforations tion through
Squeezed at 1380. Took bradenhead with 7-30-44.	ed plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 700% to start an 200% pressure.	tained. (Cross out incorrect words.) RK DONE AND RESULTS OBTAIN O sacks cement through d obtained good circuls	Perforations tion through PO' at 2 PM
Subscribed and sworn to be DETAIL Squeezed at 1380'. Took bradenhead with 7-30-44.	ed plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 700% to start an 200% pressure.	RK DONE AND RESULTS OBTAIN O sacks cement through dobtained good circuls Pumped plug down to 136 I hereby swear or affirm the above is true and correct.	perforations tion through o' at 2 PM
Subscribed and sworn to b	d plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 700% to start an 200% pressure.	RK DONE AND RESULTS OBTAIN O sacks cement through dobtained good circuls Pumped plug down to 136 I hereby swear or affirm the above is true and correct.	perforations tion through O' at 2 PM Fool Foresan the information given
Subscribed and sworn to b	d plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 700% to start an 200% pressure.	RK DONE AND RESULTS OBTAIN O sacks cement through d obtained good circuls Pumped plug down to 136 I hereby swear or affirm the above is true and correct. Name Position Engineer Representing George	perforations tion through O' at 2 PM Pool Foresan t the information given Livermore,
Squeezed at 1380. Took bradenhead with 7-30-44. Witnessed by Gordon No.	ed plan was (was not) ob ED ACCOUNT OF WO 30 sacks mud, 25 700% to start an 200% pressure. Sind George Defore me this	RK DONE AND RESULTS OBTAIN O sacks cement through d obtained good circuls Pumped plug down to 136 I hereby swear or affirm the above is true and correct. Name Position Engineer Representing George	perforations tion through O' at 2 PM Fool Foresan the information given Livermore, ompany or Operator

HONER HALL CANDON CONTRACTOR OF THE SERVICE OF THE

The state of the s

1 -