

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

E-732X

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amini Oil Corporation	8. Farm or Lease Name Anderson State
3. Address of Operator 400 Wall Towers West Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER B, 1980 FEET FROM THE East LINE AND 660 FEET FROM THE North LINE, SECTION 35 TOWNSHIP 10-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4204 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-03-72 Moved in csg. pulling unit.
- 1-06-72 Pulled 319 jts. 2 7/8" tbg. Pump rubber plug & spotted 30 sk plug @ 9710' and filled hole w/mud.
- 1-07-72 Weld on lift nipple - jack on 4 1/2" csg.
- 1-08-72 Shot 4 1/2" csg. @6010' work 4 1/2" csg. on jacks
- 1-10-72 Shot csg. @ 4500' Spotted 25 sk plug @ 4220' inside 4 1/2" csg. Weld on new 1 ft nipple.
- 1-11-72 Pulled 44 jts 4 1/2" csg. Set 25 sk plug @ 1389' - 4 1/2" stub. Weld on 8 5/8" lift nipple. Shot 8 5/8" csg. @1015'. Spotted 25 sk plug @ 1015' - 8 5/8" stub.
- 1-12-72 Spotted 50 sk plug @ 850'. Pulled 8 5/8" csg. to 320' (994' total pulled)
Spotted 50 sk plug @ 320'. Set 10 sk plug @ surface & installed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Karin Bodwin TITLE Agent DATE 2-25-72

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: