.....

(<u>, </u>			1	* . <u>1</u>			;			Ciller	net 7/1/88) Nem C-166)
						NEW MEXI	\mathbf{c}		SERVATION	CON	MISSION	
					and the second se	OBBS OFFI	-					
- + - +						en an	7 28 M 10 - 1954 -	···· 10				
			-		1962	JUN 13 Å	M 10	EL2	RECORD	1		
					Mail to Dis	trict Office, Oil	Conse	rvation Co	mmission, to v	vhich l	Form C-101 was	sent not
					later than ty	venty days after	comple	tion of we	Il. Follow instru	uctions	in Rules and R Land submit 6	egulations
LOCA	AREA 640 A Ate well c	CRES ORREC	TLY									ŗ
		Cabo	t Cor	por	ation		••••••		Mary	E11	en Dallas	*****
		(0000))	33-E	
										-	·····	
ell is											South	
											6-7	
											be kept confider	
). 1, from.	86	570	t	0		L SANDS OR			470	t o	9480	

					IMPOI	BTANT WATE	B SANI	DS				
clude data	on rate of	water i	nflow and	eleva	tion to which	water rose in ho	le.					
. 1, from	1	1,2	20	•••••	to	11,261	Ļ		feet			
. 2, from.					to			••••••	feet		•••••	
. 3, from		••••••		••••••	to		•••••		fcet			•••••••••••••••••
. 4, from				•••••••••	to			••••	feet			
						CASING RECO	RD					r.,
SIZE	WEIG PER P	HT TOOT	NEW (USE)) R D	AMOUNT	KIND OF SHOE	CU PULI	T AND LED FROM	PERFORATI	ONS	PURPOS	
20*	94	#	Used	l	25			•			Conducto	
13-3/8 8-5/8		井 - つ <i>れ</i> 山	New		329	Hallibur			• 	<u>i</u>	Surface	
5-1/2		20#	Mew		<u>3798</u> 9556	Hallibur Larkin	ton		9470-94	70	Intermed	
									<u>_</u>	• <u></u>	MAA OLLL	
SIZE OF HOLE	SIZE OF CASING		HERE Set	N OI	O. SACKS	AND CEMENT METHOD USED			MUD RAVITY		AMOUNT OF MUD USED	
22"	20*	+	25									
74"	13-3/8	1	329		350	Pump & P	lug		*** ***			
	8-5/8	1	798		250	Pump & P	lug		•			
7-7/84	5-1/2		556		200	Pumo & F	lug	l				

RECORD OF PRODUCTION AND STIMULATION

(Record the Process used, No. of Qts. or Gals. used, interval treated or shot.)

..........

Treated perforations 9475-9484 with 500 gals. mud acid.

Result of Production Stimulation.....

.....

Depth Cleaned Out

SCORD OF DBULLSTEM AND SPECIAL 1 8

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto

			TOOLS	JSED		
Rotary tools we	ere used from	0 feet	11,261	feet, and from	feet to.	feet.
Cable tools wer	re used from	feet	t o	feet, and from	feet to.	feet.
			PRODUC	TION		
Put to Produci	ng	6-12	, ₁₉ .62			
	The production d	luring the first 24 ho	24 Durs was		rels of liquid of which	
					; and	
	Gravity	46 0	••••••			•
GAS WELL:	The production d	luring the first 24 ho	ours was	M.C.F. pl	u\$	barrels of
	liquid Hydrocarb	on. Shut in Pressure	lbs.			

Length of Time Shut in.....

PLEASE INDICATE BELOW FORMATION TOPS (IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE):

	Southeastern N	Northwestern New Mexico			
Т.	Anhy	т.	Devonian 11,198	т.	Ojo Alamo
Т.	Salt	T.	Silurian	T.	Kirtland-Fruitland
B.	Salt	Т.	Montoya	T.	Farmington?
Т.	2477 Yates	Т.	Simpson	Т.	Pictured Cliffs
Т.	7 Rivers	Т.	McKee	Т.	Menefee,
Т.	Queen	Т.	Ellenburger	T.	Point Lookout
Т.	Grayburg	Т.	Gr. Wash	Т.	Mancos
Т.	San Andres	т.	Granite	T.	Dakota
Т.	Glorieta	Т.		T.	Morrison
Т.	Drinkard	Τ.		т.	Penn
Т.	Tubbs	Т.		Т.	<u></u>
Т.	Abo	Т.		Т.	
	Penn		·	T.	
Т.	Miss. 10,620	Т.		T.	
			FORMATION RECORD		х. Х

FORMATION RECORD

From	То	Thickness in Feet	Formation	From	То	Thickness in Feet	Formation
0 30 1693 1770 2477 3733 5132 7296 8510 10377 10620 11144 11198	8510 10377	1663 77 707 1256 1399 2164 1214 1867 243 524 54	Anhydrite Salt & Anhydrite Sand, Shale & Anhydri Dolimite, Anhydrite, Dolmite, Limestone & Dolmite, & Shale Limestone, Shale & Ch Sand, Shale & Chert Limestone & Chert Sand, Shale & Limesto	te Shale Sand nert	4 I.1	eston	

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far Par CIGa as can be determined from available records. 6-14-62

Cabot Corporation	Addres Box 4395, Midland, Texas
Name Percy C. O'Quinn	Poside to Take Dist. Prod. Sup!t.

5	they l	- (<i>Y</i>	um	D=14-6	ζ
	C			(Dat	6)
Address	Box	4395,	Midland	, Texas	