

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator Cabot Corporation		8. Farm or Lease Name Humble State	
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240		9. Well No. 1	
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> N.M.P.M.		10. Field and Pool, or Vaguet N. Bagley (Penn)	
15. Elevation (Show whether DF, RT, GR, etc.) 4254' D.F.		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx cement plug from 8668'-8689'.
2. Spotted a 25 sx cement plug @ 5 $\frac{1}{2}$ casing stub @ 6150'.
3. Spotted a 25 sx cement plug @ 9-5/8 casing shoe @ 3800'.
4. Spotted a 25 sx cement plug @ 9-5/8 casing stub @ 1015'.
5. Spotted a 25 sx cement plug @ 13-3/8 casing shoe @ 350'.
6. Spotted a 10 sx cement plug @ surface w/marker.
7. Hole was loaded w/mud-laden fluids.
8. Well was plugged & abandoned on 4/26/72.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Heinrich</u>	TITLE <u>Agent</u>	DATE <u>5/10/72</u>
APPROVED BY <u>John W. Rung</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 11 1972

OIL CONSERVATION COMM.
HOBBS, N. M.