,	~	~	30-025-01010
NO. OF COPIES RECEIVED			1
DISTRIBUTION			Form C-103 Supersedes Old
SANTA FE			C-102 and C-103
FILE		ISERVATION COMMISSION	Effective 1-1-65
U.S.G.S.			
LAND OFFICE			5a. Indicate Type of Lease
OPERATOR			State X Fèe
			5. State Oil & Gas Lease No.
			E-1442
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			
1. OIL X GAS WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
Amerada Hess Corporation			State BT "K"
3. Address of Operator			9. Well No.
Drawer "D", Monument, New Mexico 88265			1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM			Bagley Penn
THE West	E, SECTION 34 TOWNSHIP 11		
	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12. County
4265' DF		Lea	
6. C	hook Appropriate Day To I. I.		
NOTICE	heck Appropriate Box To Indicate]	Nature of Notice, Report or	Other Data
NOTICE	OF INTENTION TO:	SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	A STAR AND A STAR OF MENT
		OTHER	
OTHER			
	leted Operations (Clearly state all pertinent det		

Pulled tubing and flow valves. Set 2" DR plug in Model "D" packer at 8864'. Dumped 35' cement on top of plug. Shot and pulled 5-1/2" OD casing from 4230'. Ran tubing and set 70 sx. cement plug at 4230'. Cut 8-5/8" casing at 1010'. Pulled 8-5/8" casing. Set 70 sx. cement plug at 1050' and 70 sx. cement plug at 350'. Spotted 10 sx. cement plug at surface with dry hole marker. Well Plugged and abandoned.

18. I hereby certify that the information above is true and complet	te to the best of my knowledge and belief.	DATE	1-10-74	
APPROVED BY John W. Mungory	TITLE Geologis	DATE	0CT 7	197-1