

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01012 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E26
7. Lease Name or Unit Agreement Name STATE BT 'N'
8. Well No. 1
9. Pool name or Wildcat SILURO DEVONIAN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator DRAWER D, MONUMENT, NEW MEXICO 88265	

4. Well Location Unit Letter <u>P</u> : <u>660'</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>34</u> Township <u>11S</u> Range <u>33</u> NMPM <u>LEA</u> County <u></u>	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4258' DF
--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLAN TO MIRU WIRELINE UNIT. TIH W/5-1/2" GAUGE RING TO 10,800' & TOH. TIH W/CIBP & SET 10,800'. TIH W/BAILER & DUMP 2 SKS. OF CEMENT ON PLUG, TOH. FILL HOLE W/2% KCL WATER AND SURFACTANT AS PACKER FLUID. PRESSURE TEST CSG. TO 500# FOR 30 MIN. & OBTAIN CHART.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Trenedy S. Grovey TITLE SR. PETROLEUM ENGR. DATE 3-23-93

TYPE OR PRINT NAME TRENEDY S. GROVEY TELEPHONE NO. (505) 393-2144

(This space for State Use)

APPROVED BY ORIGINAL RECEIVED BY JERRY SEXTON TITLE DATE MAR 24 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 2 8 1993

CCD R3876 6000 *