

DUPLICATE

OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

Miscellaneous Reports on Wells

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

August 11, 1950

Monument, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the
Amerada Petroleum Corporation State **BT "C"** Well No. **2** In the

C/W/4 SE/4 Company or Operator of Sec. **35**, T. **11-S**, R. **33-E**, N. M. P. M.,
Bagley-Silure/Devonian Field **Lea** County.

The dates of this work were as follows: **August 8 to 10, Inc'l., 1950**

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on **August 7,** 19**50**

and approval of the proposed plan was ~~obtained~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

11,715' - Total Depth - Line. Ran Schlumberger's Electrical, Gamma Ray & Dipmeter Surveys. Cement plug from 11715' to 11586' w/35 sacks Starcor cement and from 8810' to 8681' with 35 sacks Starcor cement, cement plug from 3800' to 3688' w/35 sacks Reg. cement, cement plug from 1450' to 1370' w/25 sacks Reg. cement. Cut 8-5/8" casing off at 1300' & recovered 1296'. Cement plug from 315' to 272' w/35 sacks Reg. cement. Plugged top of casing, 13-3/8", w/10 sacks cement. Set a piece of 4" Line Pipe, cemented in center of surface casing, 5' above ground. Heavy mud between above plugs. Well plugged and abandoned at 9 A.M., 8-10-50.

Witnessed by **C. E. Nichols** Name **Amerada Petroleum Corporation** Company **Farm Boss** Title

Subscribed and sworn before me this

11th day of **August**, 19**50**

Notary Public

My commission expires **10-24-53**

I hereby swear or affirm that the information given above is true and correct.

Name **Law Topp**

Position **Assistant District Superintendent**

Representing **Amerada Petroleum Corporation** Company or Operator

Address **Drawer D, Monument, New Mexico**

Remarks:

APPROVED
AUG 15 1950

Ray Topp Name

Oil & Gas Inspector Title