ATTACHMENT TO FORM C-140 COLLINS & WARE, INC. STATE BT C No. 3

IV. Workover performed to clean-out wellbore, add 5040' of tubing and replace rod pumping equipment with an electric submersible pump.