

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9950	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name State BT"A"
3. Address of Operator 1209 South Main, Lovington, New Mexico		9. Well No. 2
4. Location of Well UNIT LETTER <u>G</u> <u>1980'</u> FEET FROM THE <u>North</u> LINE AND <u>1980'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>12-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Wildcat Bagley-Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) 4249' D.F.		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

State BT"A" #2 - Cut 5-1/2" Csg. @ 3636' and spot 35 sack plug through 2-3/8" tubing 3650' to 3550'. Spot 10 sack plug 0' - 40' in 7-5/8" Csg. and installed Dry Hole Marker and cleaned location. Csg. was loaded with Salt-Water Mud.
Work completed 1-30-73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Henderson TITLE Area Supt. DATE 3-19-73

APPROVED BY John W. Rynear TITLE _____ DATE _____

APPROVAL, IF ANY: