

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
NM 211

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
Name of Operator Sun Exploration & Production Co.	8. Farm or Lease Name State "C" A/C-1
Address of Operator PO Box 1861 Midland, Texas 79702	9. Well No. 5
Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 12-S RANGE 33-E N.M.P.M.	10. Field and Pool, or Wildcat Bagley Penn
15. Elevation (Show whether DF, RT, CR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPER. ☐
FULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☒ T.A'd well
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDON WEN ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-28: MIRU Xpert W.S.
10-29: RIH w/ 6-1/8" cut rite Shoe, 1 JT 6" Wash pipe, 1-6-1/8" stab., 1 JT 5-3/4" Wash pipe, 1- 6-1/8" Stab. 4 Jts 5-3/4" Wash pipe, 4-3/4" Bowen oil jars, 6-4-3/4 DC's on 2-7/8" W.S. to 8000'.
10-30: Finish in hole w/ milling eqpt and 2-7/8 tbg. Tag & mill 8760-8764, (1000*WT, 90 RPM. Reverse circ., full returns)4' in 3 hrs. Shoe torquing up, Rec. form cuttings & few metal cutting, raise mill to 8734, Dragging 10,000#, Lower mill back to 8764, Reaming down slowly, still torquing & dragging, Circ CLN raise shoe to 7500'.
11-2: POH w/ 2-7/8 WS, DC's & all milling eqpt. Laying down, NU well head. Close well in (TA'd well).

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Acct'g Assist II DATE 11-17-82
APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT I DATE NOV 24 1982
CONDITIONS OF APPROVAL, IF ANY: