	<b>,</b> ·	_		
NO. OF COPIES RECEIVED			Form C-103 Supersedes Old	
SANTA FE	NEW HEXICO OU CONSERV	A = 1 = 1 = 2 = 1 = 1 = 1 = 1 = 1 = 1 = 1	C-102 and C-103	
FILE	NEW MEXICO OIL CONSERVA	ATION COMMISSION	Effective 1-1-65	
U.S.G.S.				
LAND OFFICE	<del>-   -  </del>		5a. Indicate Type of Lease	
OPERATOR			State Fee X	
			5, State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)				
OIL X GAS WELL	OTHER- P&A		7. Unit Agreement Name	
2. Name of Operator			8. Farm or Lease Name	
	ada Hess Corporation		W.E. Mathers	
Address of Operator			9. Well No.	
Drawer "D", Monument, New Mexico 88265			1	
Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTER H	662 FEET FROM THE East	1980	Bagley Penn	
	, section 3 township 12-S			
	15. Elevation (Show whether DF, R. 4254 DE G.R.		12. County Lea	
C.	neck Appropriate Box To Indicate Nature	of Notice Report of O	the Dee	
NOTICE	OF INTENTION TO:	SUBSEQUEN	NT REPORT OF:	
PERFORM REMEDIAL WORK		EDIAL WORK	ALTERING CASING	
PULL OR ALTER CASING		MENCE DRILLING OPNS,	PLUG AND ABANDONMENT	
ОТНЕЯ	ОТ	THER		
7. Describe Proposed or Compl- work) SEE RULE 1103.	eted Operations (Clearly state all pertinent details, and	d give pertinent dates, includin	g estimated date of starting any proposed	

Spotted 50 ax. cement plug in 5-1/2" casing from 8620' to 9020'. Eoaded hole with salt water mud. Cut 5-1/2" casing at 3200'. Spotted 70 sx. cement plug from 2990' to 3200'. Cut 8-5/8" casing at 1004'. Spotted 70 sx. cement plug from 947' to 1052', 70 sx. cement plug from 216' to 351' and 20 sx. cement plug from surface to 24'. Installed dry hole marker. Well Plugged and abandoned.

e best of my kn	owledge and belief.			
e best of my kn	owledge and belief.			
e best of my kn	owledge and belief.			
Supver.		vices	DATE	5-30-73
E	<u> </u>		DATE	
		É	Supver., Admin. Services	. Qualification