

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 23 11 55 AM '66

| | | |
|------------------------------|--------------------------------|---|
| 5a. Indicate Type of Lease | State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator SUN OIL COMPANY | 8. Farm or Lease Name Meta Schmidt |
| 3. Address of Operator P. O. Box 2792 Odessa, Texas | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>9S</u> RANGE <u>34E</u> NMPM. | 10. Field and Pool, or Wildcat Jenkins, Wolfcamp |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4267 RT | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed plugging procedure to start about Sept. 1, 1966
Move in and rig up casing pullers.
Pick up 2" tbg., open ended, and run to 9697 - circ. with mud (gel & water).
Spot 25 sk cement plug 9515-9725 across perms - pull tbg.
Shoot 5½" csg. @ 8300 and pull.
Run tbg. open ended - spot 25 sk cement plug 8380-8250.
Spot 25 sk plug top of Tubb (6870-6790), 25 sk plug top of Glorietta (5314-5234).
Spot 25 sk plug 4140-4060; 40' in & out of 8-5/8" csg. seat - pull tbg.
Shoot 8-5/8" csg. @ 950' and pull.
Run tbg. and spot 52 sk plug 1000-950; 50' in & out of 8-5/8" csg.
Spot 75 sk plug 495-395; 50' in & out of 13-3/8" csg. spot 10 sks @ surface.
Install 10' abandonment marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J E Edgim TITLE Superintendent DATE 8-19-66

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: