

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 23 1 15 PM '66

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Meta Schmidt	
9. Well No. 1	
10. Field and Pool, or Wildcat Jenkins, Wolfcamp	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator SUN OIL COMPANY	
3. Address of Operator P. O. Box 2792 Odessa, Texas	
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>9S</u> RANGE <u>34E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4267 RT	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed plugging procedure to start about Sept. 1, 1966
Move in and rig up casing pullers.
Pick up 2" tbgs., open ended, and run to 9697 - circ. with mud (gel & water).
Spot 25 sk cement plug 9515-9725 across perfs - pull tbgs.
Shoot 5 1/2" csg. @ 8300 and pull.
Run tbgs. open ended - spot 25 sk cement plug 8380-8250.
Spot 25 sk plug top of Tubb (6870-6790), 25 sk plug top of Glorietta (5314-5234).
Spot 25 sk plug 4140-4060; 40' in & out of 8-5/8" csg. seat - pull tbgs.
Shoot 8-5/8" csg. @ 950' and pull.
Run tbgs. and spot 52 sk plug 1000-950; 50' in & out of 8-5/8" csg.
Spot 75 sk plug 495-395; 50' in & out of 13-3/8" csg. spot 10 sks @ surface.
Install 10' abandonment marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J E Edm TITLE Superintendent DATE 8-19-66
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: