NO. OF COPIES RECEIVED	· · · · · · · · · · · · · · · · · · ·	
		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		Firective 1-1-22
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oil & Gas Lease No.
		1
(DO NOT USE THIS I	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. LE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL & GA		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
BTA Oil	Producers	Hutch 7101 JV-D
3. Address of Operator	,	9. Well No.
104 Sout	h Pecos, Midland, Texas 79701	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER "D"	660 FEET FROM THE North LINE AND 660 FEET FROM	
THE West	LINE, SECTION 10 TOWNSHIP 9-S RANGE 34-E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16.	4250 GL, 4262 KB	Lea
	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
NOT	ICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
г	+	
PERFORM REMEDIAL WORK	PLUG AND ABANCON PEMEDIAL WORK	ALTERING GAGING
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	COMMENCE DRILLING OPNS. X CHANGE PLANS CASING TEST AND CEMENT JOB OTHER TIE-IN to CA	PLUG AND ABANDONMENT sing stub
TEMPORABILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or C	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Tie-in to Ca Completed Operations (Clearly state all pertinent details, and give pertinent date.; including	PLUG AND ABANDONMENT sing stub
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Tie-in to Ca Completed Operations (Clearly state all pertinent details, and give pertinent date.; including	PLUG AND ABANDONMENT sing stub
OTHER 17. Describe Proposed or C work) SEE RULE 1103 2-20-71 thru	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Tie-in to Ca Completed Operations (Clearly state all pertinent details, and give pertinent date.; including	estimated date of starting any propose. o 6575'. bowl & 5½" stub lled out
OTHER 17. Describe Proposed or C work) SEE RULE 1103 2-20-71 thru	Commence Drilling Opns. Change Plans Casing Test and cement July OTHER Tie-in to ca Completed Operations (Clearly state all pertinent details, and give pertinent dates, including) Re-spud at 12:00 Noon 2-20-71. Cleaned out to Cut & pulled 5½" casing at 6260'. Ran casing 149 joints 5½" O.D., 17#, J-55 & latched onto @ 6260'. Put 25,000# on bowl - held OK. Dricement & washed down to 9628'. Ran 2-3/8" tu 9616' & released rig. Acidized (old perfs) 9601-06' w/2000 gal 15% Swabbed back load wtr w/trace oil. Ran 2-3/8	estimated date of starting any proposed o 6575'. bowl & 5½" stub lled out bing @ CRA. " tubing

CONDITIONS OF APPROVAL, IF ANY:

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE DUPERVISOR DISTRICT

Production Clerk

24 **(**%)

3/31/71

APR

RECEIVED

APR 11971

OIL CONSERVATION COMM, HOBBS, N. 12.